

TOWNSHIP 31 RANGE 05 POINT IDENTIFIER # 340500

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 9 and 16

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Original - W.H. Byars, under contract # 456 survey dated July 28, 1882 (DCSO rec. Vol. 19 Page 7929)

-----  
Marked a Fir tree, 4" dia., with a blaze and  $\frac{1}{4}$  S on N. side for the  $\frac{1}{4}$  sec. cor., from which

A Fir 5" dia., bears North, 22 lks. dist. mkd.  $\frac{1}{4}$  S BT.

A Fir 8" dia., bears S.4°W., 18 lks. dist. mkd.  $\frac{1}{4}$  S BT.

Survey by Richard L. Templin, Jr. - Sept. 3, 1957 - C.S. File 42/303

-----  
Found - 6" Fir corner tree, askew. Blaze healed and not opened.

8" Fir, North, 22 lks. blaze healed and not opened.

12" Fir S.4°W., 18 lks. blaze healed and not opened.

Set alum. poster tag on this tree, 4" x 5 5/8".

Survey by Victor S. King - Wit: Chester C. Jones - For: Bate Lumber Co. - Feb. 5, 1959 - C.S. File 42/425-1

-----  
Found - 16" W.Fir S.4°W., 18 lks. (since destroyed by logging).

6" W.Fir tree monument for the corner. Blown down but still green. I chopped into the North face and disclosed the scribing " $\frac{1}{4}$ S". I chopped off the top leaving about a 4 ft. stump as a memorial. The negative of the scribing is retained in our office.

Set 1 $\frac{1}{2}$ " Iron pipe, 48" long, 36" in the ground.

Due to the fact that there are no trees to the South, I set 2 new bearing trees in Section 9:

12" W.Fir N.64°W., 41.3 ft. scribed  $\frac{1}{4}$  S9 BT.

12" Yew N.74°E., 38.5 ft. scribed  $\frac{1}{4}$  S9 BT.

Douglas Co. Surveyors Office - John M. Powell, Frank Jones and Joe Brady - May/June 1966 - C.S. File 54/25-20

-----  
Found - 1 $\frac{1}{4}$ " Iron pipe at corner.

12" W.Fir now 13", N.64°W., 41.3 ft. shows good scar.

12" Yew now 11", N.74°E., 38.5 ft. scribe visible " $\frac{1}{4}$  S9 BT".

Corner tree stump scribe visible " $\frac{1}{4}$ S".

Set Brass cap at cor. mkd: County Surveyors Office

$\frac{1}{4}$   $\frac{S\ 9}{S\ 16}$   
1966

All BTs in good condition. Logging Rd. bears South, 25.0 ft.

TOWNSHIP 31 RANGE 05 POINT IDENTIFIER # 340500

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 9 and 16

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Cor. Fd. OK, by BLM resurvey, by Berry and Akin, 1972-73  
(DCSO records, Vol. 38 Page 15686)

David Edwards - Brant Miller & Eric Sprinkle, Crew - 9/6/2019  
- C.S. File 65/104-3

-----  
Found - 1966 D.C.S. brass capped iron pipe.  
          No bearing trees remain.  
New - An 11" dia. Fir scribed "¼ S16 BT" bears S.48°W.,  
          20.0 ft.  
       An 18" dia. Fir scribed "¼ S9 BT" bears N.50°E.,  
          12.0 ft.  
Note - Compass decl. 15°E.