

PRIMARY CORNER DESCRIPTION Sec. Cor. for 15, 16, 21 and 22

Alias	Description
_____	_____
_____	_____
_____	_____
_____	_____

Original - W.H. Byars, under contract # 456 survey dated July 28, 1882 (DCSO rec. Vol. 19 Page 7918)

Set a stone, 14x10x8 ins., 9" in ground for cor. to secs. 15, 16, 21 and 22, marked with 3 notches on the South & East edges, from which

- A Cedar 18" dia., bears N.61°E., 32 lks. dist., marked T31S R5W S15 BT.
- A Fir 24" dia., bears S.66°E., 21 lks. dist., marked T31S R5W S22 BT.
- A Laurel 12" dia., bears S.80°W., 61 lks. marked T31S R5W S21 BT.
- A Fir 20" dia., bears N.22°W., 64 lks. dist., marked T31S R5W S16 BT.

Survey by Victor S. King - For: Bate Lumber Co. - Aug. 11, 1960 - C.S. File 51/56-11

Found - Wood stake in mound of stone.
Cedar snag with old X, before the burn.
2 Fir stump holes, a stool of Madrona. These all fit the bearing and distance for the orig. BTs.
No scribing anywhere.

There is a blazed line coming in from the South. Found 1 original blaze, 692 ft. North of the corner.

Set 1" Pipe, 30" long in a mound of stones.

Scribed the following new bearing trees:

- 4" Live Oak N.72½°W., 16.5 ft. scribed T31S R5W S16 BT.
- 6" Madrona S.84½°W., 36.1 ft. scribed T31S R5W S21 BT.
- 8" Madrona S.52°E., 8.1 ft. scribed T31S R5W S22 BT.
- 8" Madrona N.33°E., 28.4 ft. scribed T31S R5W S15 BT.

BLM resurvey by James Jelly and Wayne Rogers - under Group #1101 - Surveyed, Sept. 1982/May 1983 (DCSO records Vol. 45 Page(s) 17486-87)

The Sec. Cor, perpetuated and recorded by King in 1960, monumented with the original basalt stone, 14x10x8 ins., firmly set, projecting 5" above a mound of stone, 3 ft. base 1 ft. high, marked with 3 grooves on S. and E. faces, from which the remains of the original bearing trees:

A Cedar snag 30" dia., bears N.61°E., 32 lks., no marks visible.

A Fir root crown, size indeterminate, bears S.66°E., 21 lks. dist., no marks visible.

and bearing trees mkd. by King:

(Cont. Next Page)

TOWNSHIP 31 RANGE 05 POINT IDENTIFIER # 400400

PRIMARY CORNER DESCRIPTION Sec. Cor. for 15, 16, 21 and 22

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

A Madrone 9" dia., bears N.33°E., 40½ lks. dist., with scribe marks T31S R5W S15 BT visible on partially healed blaze.

A Madrone 10" dia., bears S.53°E., 12½ lks. dist., with healed double blaze.

A Madrone 8" dia., bears S.84°W., 54 lks. dist., with fragmentary scribe marks visible on partially healed blaze.

A Live Oak 7" dia., bears N.73°W., 24½ lks. dist., with scribe marks 1S R5W S16 BT visible on partially healed blaze.

At the corner point

Set an alum. post, 28 ins. long, 2½ ins. dia., 24 ins. in the ground, with alum. cap mkd:

T 31 S R 5 W	
S 16	S 15
S 21	S 22
1982	

Deposit the original stone alongside the aluminum post.

Fd. OK by Bruce Shaner, June 1992, M 112-49

David Edwards - Crew: Brant Miller & Eric Sprinkle - March 11, 2015 - C.S. File 65/87-36

Found - The 1982 B.L.M. Brass Cap.
All bearing trees are gone except for a 15" dia. Madrone which bears S.84°W., 35.6 ft having a healed face and being broken off at the top.
New - A 13" dia. Fir scribed "T31S R5W S22 BT" bears S.38°E., 43.4 ft.
A 15" dia. Fir scribed "T31S R5W S16 BT" bears N.67°W., 28.4 ft.
Six ft steel posts are set 2 ft East and 4 ft South.

Fd Ok by Ron Quimby, IE engineering - 9/2019 - C.S. 65/104-13

Ron Quimby - Crew: R. Heichel & J. Ogden - 1/2020 - C.S. File 65/104-41

Found - BLM Alum. Cap (properly marked)
15" Fir S.38°E., 43.4 ft. good scar
19" Fir N.67°W., 28.4 ft. good scar
Steel post 2.0 ft. east & 4.0 South.
New - 5/8" I.Rod N.26°E., 8.2 ft.
5/8" I.Rod S.6°E., 5.8 ft.
Both have yellow plastic cap stamped "ie engineering". Alum. post alongside.
Note - Compass decl. 15½°E. - Area badly burnt 2019