

TOWNSHIP 31 RANGE 05 POINT IDENTIFIER # 400440

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 15 and 16

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Original - W.H. Byars, under contract # 456 survey dated July 28, 1882 (DCSO rec. Vol. 19 Page 7919)

Set a stone, 12x10x8 ins., 8" in ground, marked ¼ on W. face for the ¼ sec. cor., from which

A Fir 16" dia., bears N.40°W., 6 lks. dist. mkd. ¼ S BT.

A Fir 12" dia., bears S.88°E., 13 lks. mkd. ¼ S BT.

Douglas Co. Surveyors Office - John M. Powell, Frank Jones and Terry Connell - June 1966 - C.S. File 54/25-14

Found - 16" now 38" D.Fir, N.40°W., 4.0 ft. bark scribed, dist. from face.

No trace of SE BT.

Set Brass cap at cor. mkd: County Surveyors Office

T 31 S R 5 W

¼ S 16 | S 15

1966

New BT - 14" D.Fir N.66°E., 22.0 ft. mkd. ¼ S15 CS BT.

Reblazed: 38" D.Fir N.40°W., 4.0 ft. scribed ¼ S16 CS BT.

Corner lies about 66.0 ft. South of ravine.

Fd. OK, by BLM resurvey by Jelley and Rogers, Surveyed Sept. 1982/May 1983 (DCSO records, Vol. 45 Page 17487)

Ron Quimby - Crew: R. Heichel & J. Ogden - 2/2020 - C.S. File 65/104-50

Found - DCSO brass cap (properly mkd)
38" D.Fir stump N.40°W., 4.0 ft.

New - 5/8" I.Rod N.52°E., 5.0 ft.

5/8" I.Rod S.73°E., 5.0 ft.

5/8" I.Rod S.6°W., 5.0 ft.

5/8" I.Rod S.70°W., 5.0 ft.

All rods have yellow plastic cap stamped "ie engineering". 5' Alum. post alongside.

Note - Area badly burnt 2019

Compass decl. 15½°E.