

TOWNSHIP 31 RANGE 05 POINT IDENTIFIER # 400640

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 3 and 4

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

Original - W. P. Wright, under contract #281 dated May 16, 1878 (DCSO records Vol. 19 Page(s) 7891)

-----  
Marked a Red Fir 14" dia., for  $\frac{1}{4}$  sec. cor., from which  
A Fir 10" dia., bears S.79°E., 12 lks.  
A Fir 10" dia., bears N.11°W., 14 lks.

BLM Corrective Resurvey - John Jelley, Lynn Roseberry, Floyd Brooks, Under Group #s 320 and 614, - Surveyed June 1966 through May 1968. (DCSO records Vol. 35 Page(s) 14367)

-----  
Point for the  $\frac{1}{4}$  sec. cor., at proportionate distance; there is no remaining evidence of original corner.  
Set an iron post, 28 ins. long,  $2\frac{1}{2}$  ins. dia., 24 ins. in the ground to solid rock, and in a mound of stone, 4 ft. base, to top with brass cap mkd: T 31 S R 5 W  
 $\frac{1}{4}$   
S 4 | S 3  
1966

from which  
A Fir 11" dia., bears S.86 $\frac{1}{2}$ °E., 145 lks., mkd.  $\frac{1}{4}$  S3 BT.  
A Fir 15" dia., bears N.53 $\frac{1}{2}$ °W., 148 lks., mkd.  $\frac{1}{4}$  S4 BT.

Ron Quimby - For: C & D Lumber Co. - Nov. 2014 - M166-22

-----  
Found - Brass cap per 1966-1968 BLM resurvey  
24" Fir S.86°E., 95.7' healed face  
30" Fir N.53°W., 97.7' healed face  
New - 13" Fir S.47°W., 15.6'  
13" Fir N.53°E., 13.3'  
Both scribed?