

TOWNSHIP 31 RANGE 05 POINT IDENTIFIER # 440300

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 22 and 27

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

Original - W.H. Byars, under contract # 456 survey dated July 28, 1882 (DCSO rec. Vol. 19 Page 7917)

-----  
Set Laurel post, 3 ft. long, 3" square, 15" in ground for ¼ sec. cor. marked ¼ S on North face, from which

A Fir 16" dia., bears S.29°W., 26 lks. dist. marked ¼ S BT

A Fir 22" dia., bears N.30°E., 6 lks. dist., marked ¼ S BT

Douglas Co. Surveyors Office - John M. Powell, Frank Jones and Terry Connell - June 1966 - C.S. File 54/25-12

-----  
Found - Orig. 16" D.Fir, now 24", S.29°W., 17.2 ft., faint bark scribe visible.

Orig. 22" now 30" D.Fir, N.30°E., 4.0 ft. no scribing visible.

Set Brass cap at cor. mkd: County Surveyors Office

T 31 S R 5 W

¼ S 22

S 27

1966

Reblazed and rescribed:

24" D.Fir S.29°W., 17.2 ft. mkd. ¼ S27 CS BT.

30" D.Fir N.30°E., 4.0 ft. mkd. ¼ S22 CS BT.

This corner lies 20.0 ft. East of top of ridge.

Brass cap and BTs Fd. OK by BLM resurvey by Berry and Akin, Sept. 1972-73 - DCSO records, Vol. 38 Page 15683

Ron Quimby - Crew: N. Fromdahl & J. Ogden - 9/2019 - C.S. File 65/104-6

-----  
Found - DCSO 1966 brass cap (properly mkd)

24" capped stump S.29°W., 17.2 ft.

42" D.Fir N.30°E., 4.0 ft.

New - 5/8"x30" I.Rod with yellow cap "ie engineering"  
N.41°W., 8.2 ft.

5/8"x30" I.Rod with yellow cap "ie engineering"  
S.30°W., 6.0 ft.

5/8"x30" I.Rod with yellow cap "ie engineering"  
S.41°E., 8.1 ft.

Note - Area burnt badly 2019

Compass decl. 15½°E.