

TOWNSHIP 31 RANGE 05 POINT IDENTIFIER # 500440

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 14 and 15

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Original - W.H. Byars, under contract # 456 survey dated July 28, 1882 (DCSO rec. Vol. 19 Page 7909)

Set a stone 14x8x6 ins., 10" in ground, marked ¼ on West side for the ¼ sec. cor., from which
A Cedar 16" dia., bears S.45°E., 12 lks. marked ¼ S BT.
A Fir 28" dia., bears N.62°W., 56 lks. marked ¼ S BT.

Survey by Victor S. King - Wit: Chester C Jones. For: Bate Lumber Co., Merlin, OR - Feb. 5, 1959 - C.S. File 42/425-4

Found - Stone 14 x 8 x 6", 10" in ground marked ¼ on West side. The stone appears to have never been touched since it was originally set.
Cedar snag S.45°E., 12 lks., burned and no scribing visible.
Stump hole from a Fir tree, N.62°W., 56 lks.
Set 1¼" Iron pipe 36" long, 24" in ground - it replaces the stone which is still there as a memorial. I set the following new bearing trees:
18" Fir N.41°W., 23.5 ft. scribed ¼ S15 BT.
12" Yew S.33°E., 34.5 ft. scribed ¼ S14 BT.

Douglas Co. Surveyors Office - John M. Powell, Frank Jones and Joe Brady - May 1966 - C.S. File 54/25-5

Found - Orig. stone and 1¼" Iron pipe at ¼ cor.
12" Yew now 13", S.33°E., 34.5 ft. scribe visible.
Yew is on edge of cut bank and the appearance is bad.
18" Fir now 20", N.41°W., 23.5 ft. shows good scar.
New BT - 7" D.Fir S.59°E., 11.2 ft. scribed ¼ S14 CS BT.

BLM resurvey by Daniel Berry and Charles Akin under Group #800, Surveyed Sept. 1972/June 1973 (DCSO records Vol. 38 Page(s) 15676)

The ¼ sec. cor., perpetuated and recorded by King in 1959 and further perpetuated and recorded by Powell in 1966, monumented with the original basalt stone, 14x8x6 ins., firmly set 8" in the ground mkd. ¼ on W. face, alongside of which is an iron pipe 1¼" dia., firmly set, protruding 8" above ground, from which the remains of the original bearing trees:
A decayed Cedar stump 12" dia., bears S.45°E., 12 lks. dist., no marks visible.
and bearing trees mkd. by King:
(Cont. Next Page)

TOWNSHIP 31 RANGE 05 POINT IDENTIFIER # 500440

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 14 and 15

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Ron Quimby - Crew: R. Heichel & J. Ogden - 2/2020 - C.S. File 65/104-65

Found - BLM brass cap (properly mkd)
 No trees found
New - 5/8"x30" I.Rod S.40°W., 4.2 ft.
 5/8"x30" I.Rod N.64°W., 5.3 ft.
 5/8"x30" I.Rod N.31°E., 6.0 ft.
 5/8"x30" I.Rod S.32°E., 5.3 ft.
 All rods have yellow plastic cap stamped "ie
 engineering". 5' Alum. post alongside.
Note - Compass decl. 15½°E.