

TOWNSHIP 31 RANGE 05 POINT IDENTIFIER # 500600

PRIMARY CORNER DESCRIPTION Sec. Cor. for 2, 3, 10 and 11

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Original - W.H. Byars, under contract # 456 surveyed July 28, 1882 (DCSO rec. Vol. 19 Page 7911)

Set a Dogwood post 4 ft. long, 4" square, 20" in ground, marked T31S R5W S2 on NE. face, S11 on SE. face, S10 on SW. face, and S3 on NW. face. Also five notches on South and two notches on the East angles of the same for the corner to secs. 2, 3, 10 and 11, from which

- A Laurel 12" dia., bears N.35°E., 55 lks. dist., mkd. T31S R5W S2 BT.
- A Fir 22" dia., bears S.35°E., 30 lks. dist., mkd. T31S R5W S11 BT.
- A Fir 38" dia., bears S.35°W., 13 lks. dist., mkd. T31S R5W S10 BT.
- A Dogwood 7" dia., bears N.15°W., 41 lks. dist., mkd. T31S R5W S3 BT.

Survey by Victor S. King, L.S. #442 - For: Bate Lumber Co. of Merlin, OR - April 8, 1959 - C.S. File 42/425-10

Found - 2 Fir snag bearing trees, both bark scribed.
38" Fir snag, S.35°E., 19.8 ft.
Set 1" steel reinforcing rod, 42" long, 34" in ground.
Scribed 4 new BTs as follows:
6" W.Fir N.44°W., 9.1 ft. scribed S3 T31S R5W BT.
4" W.Fir S.88°W., 9.9 ft. scribed S10 T31S R5W BT.
8" W.Fir N.87°E., 30.1 ft. scribed S2 T31S R5W BT.
6" W.Fir S.09°E., 15.5 ft. scribed S11 T31S R5W BT.

DCSO Fd. Cor. OK, John Powell, May 1966

BLM resurvey by Daniel Berry and Charles Akin under Group #800, Surveyed Sept. 1972/June 1973 (DCSO records Vol. 38 Page(s) 15679-80)

The Sec. Cor., perpetuated and recorded by Victor King in 1959, monumented with an iron rod, 1" dia., firmly set, protruding 10" above ground, from which the remains of the original bearing tree:

- A Fir snag 38" dia., bears S.35°E., 30 lks. dist., no marks visible.
- and bearing trees mkd. by King:
- A Grand Fir 14" dia., bears N.87°E., 45½ lks. dist., with healed blaze.
 - A Grand Fir 14" dia., bears S.9½°E., 24 lks. dist., with healed blaze.
 - A Grand Fir 8" dia., bears S.87½°W., 15½ lks. dist., with healed blaze.
- (Cont. Next Page)

TOWNSHIP 31 RANGE 05 POINT IDENTIFIER # 500600

PRIMARY CORNER DESCRIPTION Sec. Cor. for 2, 3, 10 and 11

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

A Grand Fir 9" dia., bears N.43°W., 14 lks. dist., with healed blaze.

At the corner point

Set an iron post, 28 ins. long, 2½ ins. dia., 22 ins. in the ground, with brass cap mkd:

T 31 S R 5 W
S 3 | S 2
S 10 | S 11
1973

Deposit iron rod alongside iron post.

BLM dependent resurvey by Markell G Hamm, Cadastral Surveyors, under Group #2927, surveyed June/Sept. 2017 - (DCSO records Vol. 59 Page(s) 23724)

The cor. of secs. 2, 3, 10, and 11, reported by Berry & Akin in 1973, monumented with an iron post, 2½" dia., firmly set, projecting 1" above ground, with a brass cap (properly) mkd. from which new bearing trees

A grand fir, 9" dia., bears N.69½°E., 10.0 ft., mkd. T31S R5W S2 BT.

A grand fir, 8" dia., bears S.38¾°E., 17.1 ft., mkd. T31S R5W S11 BT.

A grand fir, 4" dia., bears S.41°W., 18.0 ft. mkd X S10 BT
No suitable bearing trees available in sec. 3.

Each new BT has a 2½"x ¼" magnetic nail (Mag Nail) driven at the base right side-center & each monument established or remonumented has a magnet deposited in a white plastic case at the base of the stainless steel post. Alum. Angle iron driven alongside each monument.

Ron Quimby - Crew: R. Heichel & J. Ogden - 2/2020 - C.S. File 65/104-54

Found - BLM brass cap (properly mkd)
20" Fir N.87°E., 30.0 ft. (burnt)
20" Fir S.9½°E., 15.8 ft. (burnt)
12" Fir S.87½°W., 10.2 ft. (burnt)
14" Fir N.43°W., 9.2 ft. (burnt)

New - 5/8" I.Rod N.32°W., 4.5 ft.
5/8" I.Rod N.48°E., 8.8 ft.
5/8" I.Rod S.18°E., 4.5 ft.
5/8" I.Rod S.56°W., 5.2 ft.

All rods have yellow plastic cap stamped "ie engineering". Alum. post alongside.

Note - Area badly burnt 2019
Compass decl. 15½°E.