

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Original - W.H. Byars, under contract # 456 survey dated July 28, 1882 (DCSO rec. Vol. 19 Page 7895)

Set a sandstone, 22x16x6 ins., for the corner to secs. 23, 24, 25 and 26, marked with 2 notches on South and 1 notch on East edges, from which

A Fir 46" dia., bears N.57°E., 58 lks. dist., marked T31S R5W S24 BT.

A Fir 22" dia., bears S.37°E., 55 lks. dist., marked T31S R5W S25 BT.

A Yew 12" dia., bears S.55°W., 37 lks. dist., marked T31S R5W S26 BT.

A Fir 30" dia., bears N.66°W., 60 lks. dist., marked T31S R5W S23 BT.

BLM resurvey by Daniel Berry and Charles Akin under Group #800, Surveyed Sept. 1972/June 1973 (DCSO records Vol. 38 Page(s) 15659)

Point for the sec. cor., at proportionate distance, falls on east edge of abandoned highway, 40 lks. wide, bears N.15°E. and S.; there is no remaining evidence of the original corner.

Set a brass tablet, 3¼ ins. dia., 3½ ins. stem, in drill hole, in concrete highway surface, with top mkd.

T 31 S R 5 W
S 23 | S 24
S 26 | S 25
1973

from which

A Fir 17" dia., bears N.15°E., 95 lks. dist., mkd. T31S R5W S24 BT.

A Fir 10" dia., bears S.55°E., 102 lks. dist., marked T31S R5W S25 BT.

A Fir 13" dia., bears S.22°W., 94½ lks. dist., marked T31S R5W S26 BT.

A Fir 19" dia., bears N.60°W., 123½ lks. dist., marked T31S R5W S23 BT.

Douglas Co. Surveyors Office - Randall Smith, Deputy - Stephen Flause - Oct. 28, 1985 - C.S. File 62/29-15

Found - 1973 BLM disk set flush in concrete of old abandoned Hwy 99 road surface, cap properly marked.

A 17" now 18" dia., D.Fir with a fully healed single blaze bears N.17°E., 63.8 ft. (Rec. N.15°E., 62.7 ft.)

(Cont. Next Page)

TOWNSHIP 31 RANGE 05 POINT IDENTIFIER # 600300

PRIMARY CORNER DESCRIPTION Sec. Cor. for 23, 24, 25 and 26

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

A 10" now 16" dia., D.Fir with a fully healed single blaze bears S.55°E., 66.6 ft. (Rec. S.55°E., 67.3 ft. slope measurement.)
A 13" now 18" dia., D.Fir with a fully healed single blaze bears S.22°W., 62.4 ft. (agrees w/rec.)
A 19" now 22" dia., D.Fir with a fully healed single blaze bears N.60°W., 80.0 ft. (Rec. N.60°W., 81.5 ft. face measurement.)
No new monument or accessories set.
Corner is approx. 400 ft. East of I-5 in old Hwy 99 concrete road surface.

Fd. Ok 2/2020 - R. Quimby - C.S. File 65/104-63