

TOWNSHIP 31 RANGE 06 POINT IDENTIFIER # 200100

PRIMARY CORNER DESCRIPTION Sec. Cor. for 31 & 32; 5 & 6, T32-6

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Original - George W. Hyde under Contract #54 dated Feb. 19, 1855 (DCSO records Vol. 19 Page(s) 7949)

Set post cor. to secs. 5, 6, 31 and 32, from which
A Fir 8" dia., bears N.17°W., 88 lks. dist.
A Fir 6" dia., bears N.17°E., 86 lks. dist.
Laurel 3" dia., bears S.47°W., 21 lks. dist.
(no trees near SE.)

Survey by Clifford Bryden - For: Roseburg Lumber Co. - Feb. 1960 - M 17-34

Set 3/4" x 18" I.Pipe in rock, mkd. from orig. BTs:
8" Fir N.17°W., 58.0 ft. (down, scribe visible.)
6" Fir N.17°E., 57.8 ft. (stump)
New BTs:
13" D.Fir N.81½°W., 36.0 ft.
9" D.Fir N.8°E., 69.9 ft.
6" D.Fir S.59°E., 45.0 ft.
8" D.Fir S.1½°W., 68.7 ft.

BLM resurvey by G. Steven Popken, Cadastral Surveyor, under Group #883, surveyed Sept. 8-25, 1975 (DCSO records, Vol. 37 Pages 15380-81)

The Sec. cor., perpetuated and recorded by Bryden in 1960, monumented with an iron pipe, 3/4" dia., firmly set, projecting 8" above ground, from which the remains of the original bearing tree:

A root hole, bears N.17°W., 88 lks. dist., with a down Fir alongside, 14" dia., with scribe marks T32S R6W S31 BT visible on open blaze.
and bearing trees mkd. by Bryden:
A Fir 14" dia., bears N.8°E., 106 lks. with healed blaze.
A Fir 13" dia., bears S.59°E., 68½ lks. with healed blaze.
A Fir 14" dia., bears S.1½°W., 104 lks. with healed blaze.
A Fir 16" dia., bears N.81½°W., 55 lks. with healed blaze.

At the corner point
Set an iron post, 28 ins. long, 2 1/2 ins. dia., 24 ins. in the ground, in a mound of stone, 2 ft. base, to top, with brass cap marked

T 31 S R 6 W
S 31 | S 32
S 6 | S 5
T 32 S
1975

Deposit iron pipe alongside iron post. Cont.

TOWNSHIP 31 RANGE 06 POINT IDENTIFIER # 200100

PRIMARY CORNER DESCRIPTION Sec. Cor. for 31 & 32; 5 & 6, T32-6

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Mark Smalley, L.S. #2354 - For: Kenneth Ford - Oct. 1994 - ~~M~~
~~121-7~~ M121-6

Found - 1975 Cadastral BCIP & 3/4" iron pipe.
Fir N.17°W., 58.1' down, rotten w/visible scribe OBT
29" Fir, N.81½°W., 36.0', healed.
24" ~~Fir~~ N.8°E., 69.9', healed.
12" ~~Fir~~ S.59°E., 45.0', healed.
22" Fir, S.1½°W., 68.7', healed.

Note - Also found 4 BTs referencing location of corner set
in error from 1975 survey no monument at this
location which bears N.85°E., from above noted
corner.

Added per M121-6 2/15/2023 JC

Gregg Neitsch - For: Carbon River Holdings LLC - 2/2023 -
M181-76

Found - 2½" O.D GIP with BLM ¾" BC stamped "T31S R6W S31
S32 S6 S5 T32S 1975", 8" above ground, from which
39" D.Fir with healed blaze N.81½°W., 36.0'. 1994
24" D.Fir with healed blaze N.8°E., 69.9'. 1994
18" D.Fir with healed blaze S.59°E., 45.0' 1994
30" D.Fir with healed blaze S.1½°W., 68.2'
(S.1½°W., 68.7' 1994)