

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 14 and 23

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Original - W.H. Byars, under contract # 448 survey dated June 13, 1882 (DCSO records Vol. 19 Page(s) 7975)

Set a Cedar post, 3 ft. long, 3" sq., 18" in the ground for 1/4 sec. cor. mkd. 1/4 S on N. face, from which
A Fir 36" dia., bears N.23°W., 23 lks. dist. mkd. 1/4 S BT.
A Hemlock 28" dia., bears S.16°E., 21 lks. dist. mkd. 1/4 S BT.

Douglas Co. Surveyors Office - John Powell, Frank Jones, Cliff Stone, crew - Oct. 1966 - C.S. File 54/31-12

Found - 36" now 50" D.Fir N.23°W., 15.2 ft. faint bark scribe visible "BT". (dist. to approx. face of tree) This tree will be cut.

28" Hemlock, now rotten stump, S.16°E., 13.9 ft.
Set Brass cap at cor. mkd: County Surveyors Office
T 31 S R 6 W

1/4 S 14
S 23
1966

New BTs -14" D.Fir N.72 1/2°W., 33.1 ft. mkd. 1/4 S14 CS BT.

17" Yew S.31 1/2°E., 31.0 ft. mkd. 1/4 S23 CS BT.

This corner lies 53.0 ft. West of small creek.

BLM Dependent Resurvey by Kenneth W. Saveland, Cadastral Surveyor, under Group No. 2300, Surveyed March/April 2008 - (DCSO records Vol. 56 Page(s) 22173)

The 1/4 sec. cor. of secs. 14 and 23, perpetuated by the Douglas County Surveyor's Office in 1966, monumented with an iron post, 1 1/4" dia., firmly set, projecting 15" above the ground, with brass cap (properly) mkd.

from which the remains of the original bearing trees

A decayed hemlock stump, size indeterminate, bears S.16°E., 13.9 ft., with no marks visible.

A sawed, decayed fir stump, 52" dia., bears N.23°W., 15.2 ft., with no marks visible.

and the remains of BTs mkd by the Douglas Co Surveyor's Office

A yew, 19" dia., bears S.28 1/4°E., 29.8 ft., with scribe marks 1/4 S23 CS BT visible on a partially healed blaze.

A sawed fir stump, 25" dia., bears N.71°W., 32.7 ft., with a healed blaze.

and a new bearing tree

A yew, 10" dia., bears N.83 1/2°E., 16.2 ft., mkd. 1/4 S14 BT.

Each new bearing tree has a 2 1/2" x 1/4" magnetic nail (Mag Nail) driven at the base right side-center.

Corner is located on a spur, slopes N. 10° E. cont.

TOWNSHIP 31 RANGE 06 POINT IDENTIFIER # 540400

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 14 and 23

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

From the corner, East, at:
25 ft., ravine, drains N. 25° E.
From the corner, West, at:
50 ft., creek, 5 ft. wide, course N.45°W.
The geographic position (NAD 1983 (CORS 96)) of the following corners, as determined by a tie from a temporary GPS control point, established utilizing dual frequency, carrier phase GPS receivers, using for control National Spatial Reference System Continuously Operating Reference Station (CORS) CAPE BLANCO CORS ARP (CABL), and National Cooperative CORS Network Station ROSEBURG COOP CORS ARP (DCSO), is as follows:
The corner of sections 15, 16, 21, and 22.
Latitude: 42°52'10.25" N. Longitude: 123°24'26.03" W.