

PRIMARY CORNER DESCRIPTION AP (Line Tree on East line Sec.12)

Alias	Description
_____	_____
_____	_____
_____	_____
_____	_____

<p>Original - Geo. W. Hyde, Deputy Surveyor under contract No. 54, dated Feb. 19, 1855. (DCSO records Vol. 19 Page(s) 7877)</p> <p>-----</p> <p>South on West boundary of sec. 7 (T31-5) ... @ 19.1 chains a Fir 30" dia.</p>
<p>Greg Lang for Silver Butte Timber Co. Oct. 1997 - M 128-18</p> <p>-----</p> <p>Found - 42" Fir, broken top, original line tree, two marks on each side.</p> <p>New Accessories -</p> <ul style="list-style-type: none"><li>Spike in face of 8" Fir, bears S.78°14'W., 21.19 ft. scribed "LT T31S R6W S12" "BT"</li><li>Spike in face of 11" Fir, bears N.28°51'E., 22.32 ft. scribed "LT T31S R5W S7" "BT"</li><li>Spike in face of 8½" Fir, bears S.59°31'E., 36.71 ft. scribed "LT T31S R5W S7" "BT"</li><li>5/8" iron rod with plastic cap marked "Lang Surveying" bears N.0°52'E., 5.00 ft.</li></ul>
<p>BLM dependent resurvey by Daniel E. Weller, Cadastral Surveyor, under Group #1884, surveyed July/Sept 1998. (DCSO records Vol. 53 Page(s) 20474)</p> <p>-----</p> <p>An original line tree, a fir, 42" diam., mkd. with two notches on N. and S. side, perpetuated by Lang, in 1998. <u>This now becomes an Angle Point</u>, from which a reference monument and bearing trees by Lang:</p> <ul style="list-style-type: none"><li>An iron rod, 5/8" dia., firmly set, projecting 3" above ground, bears N.0°52'E., 7½ lks., with plastic cap mkd. LANG SURVEYING.</li><li>A fir, 12" dia., bears N.30¼°E., 34½ lks., with scribe marks LT S7 T31S R5W BT visible on partially healed double blaze.</li><li>A fir, 9" dia., bears S.59½°E., 57 lks., with scribe marks LT S7 T31S R5W BT visible on partially healed double blaze.</li><li>A fir, 9" dia., bears S.77¼°W., 32½ lks., with scribe marks LT S12 T31S R6W BT visible on partially healed double blaze.</li></ul>