

TOWNSHIP 31 RANGE 07 POINT IDENTIFIER # 140100

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Sec. 31; & 6 of T32-7

| | |
|-------------|-------------------|
| Alias _____ | Description _____ |
| Alias _____ | Description _____ |
| Alias _____ | Description _____ |
| Alias _____ | Description _____ |

GLO survey by W.H. Byars, Deputy Surveyor under contract # 420 dated Sept. 16, 1881 (DCSO records Vol. 19 Page(s) 8028)

Set a Fir post 4 ft. long, 4" sq., 20" in the ground, mkd. ¼ S. on the N. side for the ¼ sec. cor., from which
A Live Oak 8" dia., bears S.28°E., 10 lks. dist.
A Sugar Pine 20" dia., bears N.40°W., 11 lks. dist.
Each marked "¼ S BT".

Douglas County Surveyors Office - James W. Byron, Surveyor
John Powell - C.S. File 54/36-21 & 24 - July 2, 1969

Corner searched for, not found.
Found old E-W brushed line. Also 2 live oaks which were opened earlier, no marks. Old Pine down, out of place with old axe work. No evidence to renew.