

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 32 and 33

Alias	Description
_____	_____
_____	_____
_____	_____
_____	_____

GLO survey by W.H. Byars, Deputy Surveyor under contract # 448 dated June 13, 1882 (DCSO records Vol. 19 Page(s) 8062)

-----  
Set a Laurel post, 4" sq., 40" long, 20" in the ground, marked ¼ S. on W. side for the ¼ sec. cor., from which  
A Fir 32" dia., bears N.3°W., 37 lks. dist. mkd. ¼ S BT  
A Laurel 10" dia., bears South 45 lks. dist. mkd. ¼ S BT

BLM resurvey by Donald Beck, Cadastral Surveyor, under Group #531 - Surveyed Oct 1963/June 1964 - (DCSO records Vol. 33 Page(s) 13636)

-----  
The ¼ sec. cor., determined at record distance from the remains of the original bearing trees:

A stump hole bears N.87°E., 45 lks. dist.; found Madrone snag, 12" dia. lying down hill from the stump hole, no marks remaining on rotted face. (Rec. brg. South)

A Fir 50" dia., bears West, 37 lks. dist. mkd. ¼ S BT on bark blaze, on East side of tree. (Rec. brg. N.3°W.)

The corner falls on a blazed line which extends North and South.

At the corner point

Set an iron post, 28" long, 2 ½" dia., 21" in the ground, with brass cap mkd:

¼  
S 32 | S 33  
T 31 S R 7 W  
1963

from which a new bearing tree:

A Fir 15" dia., bears N.57 ¾°E., 77 lks. dist. mkd. ¼ S33 BT.

BLM resurvey by James E. Jelley and Wayne L. Rogers, Cadastral Surveyors, under Group #1086, surveyed April/June 1982 (DCSO records Vol. 46 Page(s) 17553)

-----  
The ¼ sec. cor., monumented with an iron post, 2½" dia., firmly set, projecting 4" above ground, with brass cap mkd. in 1963, from which the remaining original bearing tree:

A Fir 50" dia., bears West, 37 lks. dist., with fragmentary scribe marks visible on bark blaze.

and the remains of a bearing tree mkd. by Beck:

A Fir snag 15" dia., bears N.57 ¾°E., 77 lks. dist., with fragmentary scribe marks visible on partially healed blaze.

and a new bearing tree:

A Fir 8" dia., bears N.19°E., 87 lks. dist. mkd. ¼ S33 BT.

continued next page

TOWNSHIP 31 RANGE 07 POINT IDENTIFIER # 300140

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 32 and 33

Alias	_____	Description	_____
Alias	_____	Description	_____
Alias	_____	Description	_____
Alias	_____	Description	_____

Greg Lang - Trevor Lang, Party Chief - J. Herzberg, Witness -  
October 2005 - C.S. File 65/54-38

-----

Found - Brass Cap set by BLM  
A 50" Fir bears West 24.67 ft (orig rec N.3°W.,  
24.42 ft; 1964 & 1982 BLM rec is West 24.42 ft)  
A 13" Fir bears N.19°E., 56.50 ft (1982 BLM rec is  
N.19°E., 57.42 ft)  
Fd Fir snag to the NE (rec N.57<sup>3</sup>/<sub>4</sub>°E., 50.82 ft)

New - A 21" Fir bears N.79°E., 47.10 ft scribed "¼ S33 BT"  
A 27<sup>1</sup>/<sub>2</sub>" Fir bears S.28<sup>1</sup>/<sub>2</sub>°E 43.10 ft scribed "¼ S33 BT"

Note - We set spikes in the base of all existing & new BTs  
for measuring dists to the corner; bearings to  
the trees were measured with a total station &  
are based on the 1964 resurvey of the north line  
of Section 32  
Corner lies on steep northerly slope and 950' South  
of Middle Creek Road.