

PRIMARY CORNER DESCRIPTION Sec. Cor. for 13, 14, 23 and 24

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GL0 survey by W.H. Byars, Deputy Surveyor under contract # 448 dated June 13, 1882 (DCSO records Vol. 19 Page(s) 8040)

-----  
Set Fir post, 4 ft. long, 4" sq., 24" in the ground, for cor. to secs. 13, 14, 23 and 24, marked T31S R7W S13 on NE.; S24 on SE.; S23 on SW. and S14 on NW. faces, with 1 notch on E. and 3 notches on S. edges, from which  
A Fir 14" dia., bears N.30°E., 39 lks. dist. mkd. T31S R7W S13 BT.  
A Fir 12" dia., bears S.10°E., 46 lks. dist. mkd. T31S R7W S24 BT.  
A Fir 12" dia., bears S.21°W., 40 lks. dist. mkd. T31S R7W S23 BT.  
A Fir 18" dia., bears N.20°W., 40 lks. dist. mkd. T31S R7W S14 BT.

Survey by Howard W. Johnstone - For: Roseburg Lumber Co. - Aug/Sept. 1962 - C.S. File 51/163-8

-----  
Found - 18" Fir N.20°W., 26.4 ft., now 36", bark scribe visible.  
14" Fir N.30°E., 25.7 ft., now a windfall.  
Set 3/4" x 30" I.Pipe.  
Scribed -28" D.Fir S.78°E., 16.2 ft.  
14" D.Fir S.26½°W., 68.0 ft.  
36" D.Fir N.20°W., 26.4 ft. (OBT rescribed)

BLM remonumentation by James E. Jelley, Cadastral Surveyor, under Group #350 - dated May 3, 1957 - (DCSO records Vol. 35 Page(s) 14509-10)

-----  
The Sec. cor., perpetuated and recorded by the County in 1962, monumented with an iron pipe, 1" dia., firmly set, projecting 10" above ground, from which the remaining original bearing trees:

A root hole bears N.30°E., 39 lks. dist., with a down Fir 14" dia., alongside, with fragmentary scribe marks visible on decayed blaze.  
A Fir 42" dia., bears N.20°W., 40 lks. dist. with fragmentary scribe marks visible on bark blaze. Remarked T31S R7W S14 on bark alongside the original blaze by the County Surveyor.  
and bearing trees mkd. by the County  
A Fir 31" dia., bears S.80°E., 25 lks. dist. with fragmentary scribe marks visible on open blaze.  
A Fir 17" dia., bears S.27°W., 103 lks. dist., with fragmentary scribe marks visible on open blaze.  
(Cont. Next Page)

TOWNSHIP 31 RANGE 07 POINT IDENTIFIER # 600400

PRIMARY CORNER DESCRIPTION Sec. Cor. for 13, 14, 23 and 24

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

At the corner point  
Set an iron post, 28" long, 2 1/2" dia., 24" in the ground,  
with brass cap mkd:

T 31 S R 7 W  
S 14 | S 13  
S 23 | S 24  
1969

from which new bearing trees

A Fir 30" dia., bears N.36 3/4°E., 104 lks. dist. mkd. T31S  
R7W S13 BT.

A Fir 20" dia., bears N.83 1/4°W., 118 lks. dist. mkd. T31S  
R7W S14 BT.

Reset Iron pipe alongside iron post.

BLM resurvey by Owen C. Chatters II, Cadastral Surveyor,  
under Group #834, surveyed April/June 1974 - (DCSO records  
Vol. 39 Page(s) 15734-35)

-----  
The Sec. cor., monumented with an iron post, 2 1/2" dia., firmly  
set, projecting 6" above ground with 1969 brass cap  
from which the remains of the original bearing trees:

A Fir 42" dia., bears N.20°W., 40 lks. dist., with frag-  
mentary scribe marks visible on bark; remarked T31S R7W  
S14 BT, in 1962.

and bearing trees mkd. by the County in 1962:

A Fir 35" dia., bears S.80°E., 25 lks. dist., with frag-  
mentary scribe marks visible on burned blaze.

A Fir 17" dia., bears S.27°W., 103 lks. dist., with healed  
blaze.

and the remains of bearing trees mkd. by Jelley:

A Fir stump 30" dia., bears N.36 3/4°E., 104 lks. dist.,  
with scribe marks BT visible on open blaze.

A Fir 20" dia., bears N.83 1/4°W., 118 lks. dist., with  
healed blaze.

and a new bearing tree:

A Fir 27" dia., bears N.53°E., 229 lks. dist., mkd. T31S  
R7W S13 BT.

Fd. Ok by R Quimby - 10/2017 - C.S. File 65/99-12