

TOWNSHIP 31 RANGE 07 POINT IDENTIFIER # 620700

PRIMARY CORNER DESCRIPTION W 1/16 Sec 1, & S 36 T30-7

Alias	_____	Description	_____
Alias	_____	Description	_____
Alias	_____	Description	_____
Alias	_____	Description	_____

1977 SE ref. monument now gone.
New B0s- 17" D.Fir double blazed & scribed "W 1/16 S36 CS BT"
bears N.8°E., 32.9 ft.
½" I.R. with yellow BLM plastic cap mkd: BLM" bears
N.74½°E., 217.5 ft.
Note - Corner lies 6 ft. northerly of northerly rail of R/R
tracks. See sketch in file.

Douglas Co. Surveyor's Office - Crew: Stephen J. Flause and
Jeff Lorsung - 4/1/25 - C.S. File 67/60-15

Found - ¾" BLM brass cap unreadable. Leans slightly
north, flush.
¾" BLM brass cap N.67½°W. (Rec N.71°W.) 36.3 ft
flush. This monument is approx. 1½ ft S.S.W. of
a 16" Ponderosa Pine.
24" D. Fir N.9½°E. 32.5 ft (Rec N.8°E. 32.9 ft.)
Fully healed double blaze. Add ¾" mag nail
left side center.
½" Iron rod with yellow BLM plastic cap mkd BLM
N.77°E. 217.5 ft (Rec N.74½°E.)
Corner is 6 ft northerly of northerly rail of R/R
tracks.
Bearings are local magnetic measured from corner R/R
rail likely influence compass.
New - ⅝"x30" Iron rod south 30.0 ft with yellow DCS0
plastic cap projecting 6".
Comments - Monument condition is not improved area. Is
regularly disturbed by railroad maintenance.
Compass decl. 14¼°E.
O CRS COORDINATE SYSTEM
COTTAGE GROVE-CANYONVILLE ZONE
N - 29312.967 E - 124301.627