

PRIMARY CORNER DESCRIPTION Sec. Cor. for 7 & 18; 12 & 13, T31-9

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by W.H. Byars, Deputy Surveyor under contract # 456 dated July 28, 1882 (DCSO records Vol. 19 Page(s) 8106-07)

Set a Chinquapin post 4 ft. long, 4" sq., 24" in the ground, mkd. T31S R8W S7 on the NE.; S18 on the SE.; R9W S13 on the SW.; and S12 on the NW. faces; also 4 notches on the S. and 2 notches on the N. angles of same, for the corner to secs. 7, 12, 13 and 18, from which

A Fir 15" dia., bears N.55°E., 13 lks. dist. mkd. T31S R8W S7 BT.

A Cedar 12" dia., bears S.52°E., 61 lks. dist. mkd. T31S R8W S18 BT.

A Fir 40" dia., bears S.30°W., 28 lks. dist. mkd. T31S R9W S13 BT.

A Fir 48" dia., bears N.75°W., 30 lks. dist. mkd. T31S R9W S12 BT.

GLO survey by Wm. H. Byars, Deputy Surveyor, under Contract #727, dated Dec. 20, 1900 - (DCSO records Vol. 19 Page(s) 8241)

Corner gone, witness trees standing.

Set a Fir post 4 ft. long, 4" sq., 24" in the ground mkd. T31S S7 on NE.; R8W S18 on SE.; R9W S13 on SW.; and S12 on NW. faces; with 4 notches on S. and 2 notches on N. angles.

BLM Resurvey by C. Albert White, Harold D. Corbin, Cadastral Surveyor and Donald R. Beck, Surveying Technician, Under Group #446, Surveyed Nov. 1960/Sept. 1962 - (DCSO records Vol. 31 Page(s) 13186)

The Sec. Cor., determined from the remains of the original bearing trees:

A rotted Fir stump, 27" dia., bears N.50½°E., 13 lks. dist., no marks remaining. (Rec. brg. N.55°E.)

A Cedar 30" dia., bears S.30½°E., 61 lks. dist., scribe marks S18 visible on opened blaze. (Rec. brg. S.52°E.)

A Fir 50" dia., bears S.30°W., 31 lks. dist., old axe marks visible. (Rec. dist. 28 lks.)

A rotted Fir stump, bears N.75°W., 34 lks. dist., no marks remaining. (Rec. dist. 30 lks.)

At the corner point

Set an iron post, 28" long, 2 1/2" dia., 22" in the ground, with brass cap mkd:

(Cont. Next Page)

TOWNSHIP 31 RANGE 08 POINT IDENTIFIER # 100500

PRIMARY CORNER DESCRIPTION Sec. Cor. for 7 & 18; 12 & 13, T31-9

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

T 31 S
R 9 W R 8 W
S 12 | S 7
S 13 | S 18
1962

from which new bearing trees:

- A Fir 21" dia., bears N.88°E., 29 lks. dist. mkd. T31S R8W S7 BT.
- A Fir 16" dia., bears S.42½°E., 65 lks. dist. mkd. T31S R8W S18 BT.
- A Fir 26" dia., bears S.65°W., 82 lks. dist. mkd. t31S R9W S13 BT.
- A Fir 17" dia., bears N.55°W., 35 lks. dist. mkd. T31S R9W S12 BT.

Fd. BC & BTs by C. Woodruff, 4/2008 - M156-5
Fd. by C. Woodruff, 6/2010 - M161-7

Fd. 12/2016 - By R. Quimby C.S. File 65/93-62, Cor. is in SE Cor. of clear cut unit.