

TOWNSHIP 31 RANGE 08 POINT IDENTIFIER # 500100

PRIMARY CORNER DESCRIPTION Sec. Cor. for 34 & 35; 2 & 3, T32-8

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

GLO survey by W.H. Byars, Deputy Surveyor under contract # 456 dated July 28, 1882 (DCSO records Vol. 19 Pages 8098-99)

-----  
Set a stone 18x14x10 ins., 10" in the ground mkd. with 2 notches on the E.; and 4 notches on the W. angles of same for the corner to secs. 2, 3, 34 and 35, from which

A Fir 14" dia., bears N.82°E., 57 lks mkd. T31S R8W S35 BT  
A Fir 14" dia., bears S.65°E., 41 lks mkd. T32S R8W S2 BT.  
A Fir 16" dia., bears S.28°W., 30 lks mkd. T32S R8W S3 BT.  
A Fir 13" dia., bears N.35°W., 42 lks mkd. T31S R8W S34 BT.

Douglas Co. Surveyors Office - John M. Powell, and crew - Jan. 1967 - C.S. file 54/36-73

-----  
Found - Pieces of stone at section corner.  
14" now 27" D.Fir N.82°E., 34.2 ft. (Rec. 32.6') Old axe work, no scribe visible.  
14" now 21" D.Fir S.65°E., 27.1 ft., shows good scar.  
16" now 36" D.Fir S.28°W., 19.8 ft., bark scribe visible.  
13" now 30" D.Fir N.35°W., 27.1 ft., bark scribe visible.

Set Brass cap at cor. mkd: County Surveyors Office

T	31	S	R	8	W
S	34		S	35	
S	3		S	2	
T	32	S			
					1967

Reblazed and rescribed:

27" D.Fir N.82°E., 34.2 ft. mkd. T31SR8W S35 CSBT  
36" D.Fir S.28°W., 19.8 ft. mkd. T32S R8W S3 CSBT  
30" D.Fir N.35°W., 27.1 ft. mkd. T31S R8W S34

Best way to reach corner is North on railroad to yellow tag on small Fir.

Fd. and Used in BLM Resurvey by James E. Jelley and James J. Carlson, Cadastral Surveyors, under Group #899, surveyed Aug. 1976/Nov. 1977 - (DCSO records Vol. 41 Page(s) 16185-86)

Ron Quimby - J. Leonard & N. Fromdahl Crew - 9/2013 - C.S. File 65/80-12

-----  
Condition report only

Found - 1967 DCSO brass cap

44" D.Fir S.28°W., 19.8

28" Fir S.65°E., 27.1 (now stump) (M83-26 S.62°E.)

continued next page

