

PRIMARY CORNER DESCRIPTION Cor. Secs. 16, 17, 20, & 21

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by W.H. Byars under contract #727, dated December 20, 1900 - (DCSO records Vol. 19 Page(s) 8215-6)  
-----

Set a basalt stone, 18x12x8", 12" in the ground, for cor. of secs. 16, 17, 20, & 21, mkd with 3 notches on S & 4 notches on E edges, from which

- A fir, 20" dia., bears N.30°E., 113 lks., mkd: T31S R9W S16 BT.
- A fir, 30" dia., bears S.38°E., 128 lks., mkd: T31S R9W S21 BT.
- A fir, 36" dia., bears S.45°W., 100 lks., mkd: T31S R9W S20 BT.
- A fir, 80" dia., bears N.32°W., 283 lks., mkd: T31S R9W S17 BT.

---

Clifford A. Stephens - For: Coos Head Timber Co. - Dec. 1959/Feb. 1961 - C.S. File 51/178 & M20-16  
-----

Find 2 BTs remaining. Corner falls under 60" down Fir log. Set post on East side of log from which

- 38" Fir bears S.45°W., 66.0 ft. (face not opened)
- 30" Fir bears S.38°E., 85.6 ft. (scribing visible)

The BTs in the NW & NE quadrant gone.

---

Douglas Co. Surveyors Office - John M. Powell - Frank Jones & Joe Brady - March/April 1967 - C.S. File 54/32-66  
-----

Found - Orig. 38" now 41" Fir, S.45°W., 66.0 ft. shows good scar.  
Orig. 30" now 37" Fir S.38°E., 85.6 ft., shows good scribing "S21 T31S R9W"  
No trace of NE and NW trees.

Set - Brass cap at cor. mkd: County Surveyors T31S R9W  
Office S 17 | S 16  
1967 S 20 | S 21

New BTs- 5" D.Fir S.21°W., 29.5 ft. mkd: T31S R9W S20 CS BT.  
8" D.Fir S.45°E., 15.3 ft., mkd: T31S R9W S21 CS BT.  
10" D.Fir N.53°W., 18.1 ft. mkd: T31S R9W S17 CS BT.  
8" D.Fir N.26°E., 18.6 ft., mkd: T31S R9W S16 CS BT.

---

Terrence Nickerson, Medford BLM - July 1985 - C.S. 62/24-2  
-----

Found - 1967 Douglas Co. brass cap lying on the ground.  
Orig. BT, a fir snag, 40" dia., 25 ft. high, bears S.38°E., 128 lks., to face (84.5 ft.) with scribe marks T31SR9 S21 visible on open blaze. (DCSO record of 85.6 ft. appears to be to the side center of tree) continued next page

PRIMARY CORNER DESCRIPTION Cor. Secs. 16, 17, 20, & 21

Alias	Description
Alias	Description
Alias	Description
Alias	Description

Orig. BT, a fir, 45" dia., bears S.45°W., 100 lks., to face (66 ft) with healed blaze.

1967 - A fir, 9" dia. bears N.26°E., 18.6 ft w/healed blaze

BTs A fir 11" dia. bears S.45°E., 15.3 ft w/healed blaze

A fir 7" dia., bears S.21°W., 29.5 ft w/healed blaze

A fir 16" dia. bears N.53°W., 18.1 ft w/healed blaze

Set - Reset the iron post (1"x30") 18" in the ground, to solid bedrock, in a collar of stone, 2 ft. base, 6" high. The corner point fell in the middle of a large down fir log (6 ft. dia.) I removed a section of this down log to monument the corner position.

Douglas Co. Surveyors Office - Stephen J. Flauser - John Pike  
- Oct. 8, 1992 - C.S. File 64/32-9

-----

Found - Possible original stone measuring approx. 18x12x8" (as per record) lies on north edge of 2½" dia. brass cap 1967 & 1985 Renewals. Brass cap is on a 1¾" I.P. firmly set & protruding approx. 1 ft. above a 2 ft. dia. mound of stone. (Notches not apparent on fd. stone; did not disturb stone mound to examine entire fd. stone.)

Evidence of 2 original BTs fd.; NE & NW orig. BTs gone.

A fir 30" dia. now a 25' tall 40" dia. breast high fir snag w/scrubbing "T31S R9 S21" visible on an open blaze bears S.38°E., 86.4 ft. (Orig. record S.38°E., 84.5 ft., possibly a face measurement.)

A fir 36" dia., now a 45" dia. breast high D.Fir w/fully healed blaze & various cruisers marks bears S.45°W., 68.2 ft. (Original rec. S.45°W., 66.0 ft. possibly a face meas.)

Found 4 bearing trees from 1967 Renewal

8" D. Fir now 14" D.B.H. w/fully healed double blaze bears N.26°E., 18.6 ft. (as per record).

8" D.Fir now 12" DBH w/fully healed double blaze bears S.45°E., 15.3 ft (as per rec.)

5" D.Fir now 8" D.B.H. w/fully healed double blaze bears S.21°W., 29.5 ft. (as per rec.)

10" D.Fir now 19" D.B.H. w/fully healed double blaze bears N.53°W., 18.1 ft. (as per rec.)

Note - Monument is on slight bench area of gradual NE slope and on East-West cutting lines, a partial cut to the South, a recent clear cut to North.

TOWNSHIP 31 RANGE 09 POINT IDENTIFIER # 300400

PRIMARY CORNER DESCRIPTION Cor. Secs. 16, 17, 20, & 21

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

BLM dependent resurvey by Edith M Forkner, Cadastral Surveyor, under Group #2796, surveyed Aug. 2015/March 2016 - (DCSO records Vol. 58 Page(s) 23440-2 & Plat T31-9 2017-1)

-----  
The cor. of secs. 16, 17, 20, & 21, perpetuated by the Douglas Co. Surveyor's Office in 1967; further perpetuated by Nickerson, in 1985; monumented with an iron post, 1½" dia., firmly set, projecting 12" above a collar of stone, 1½ ft. base, 8" high, with a brass cap (properly) mkd. from which the remains of the original BTs

A decayed fir snag, 32" dia., bears S.38°E., 85.5 ft., with illegible scribe marks visible on partially healed blaze. (Record and to face, 84.5 ft.)

A broken-top fir, 48" dia., bears S.45°W., 66.0 ft., with a healed blaze.

and the BTs mkd. by the Douglas County Surveyor's Office

A fir, 19" dia., bears N.25°E., 18.2 ft., with a healed blaze.

A fir, 15" dia., bears S.45¼°E., 15.6 ft., with a healed blaze.

A fir, 10" dia., bears S.21½°W., 29.1 ft., with a healed blaze.

A fir, 24" dia., bears N.53°W., 17.7 ft., with a healed blaze.

Corner is located between segments of a fallen decayed fir log, 4 ft. dia.

NAD 1983 (2011)

Latitude 42°52'03.82"N.

Longitude 123°46'48.50"W.