

TOWNSHIP 31 RANGE 09 POINT IDENTIFIER # 400140

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 33 & 34

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by W.H. Byars under contract #727, dated December 20, 1900 - (DCSO records Vol. 19 Page(s) 8201)

Mark Yew, 8" dia., S34 on E & S33 ¼ S on W faces for ¼ sec. cor., from which
 A fir, 8" dia., bears N.38°E., 32 lks., mkd: S34 ¼ S BT.
 A fir, 18" dia., bears S.42°W., 68 lks., mkd: S33 ¼ S BT.

Douglas Co. Surveyors Office - John M. Powell - Frank Jones & Joe Brady - March 1967 - C.S. File 54/32-35

Found - Orig. 8" Yew Corner Tree, scribe visible "S33" S34".
 Orig. 18", now 22" D.Fir, S.42°W. 44.8 ft., burnt face.
 Orig. 8" D.Fir, now down & tree rotted, N.38°E., 21.1 ft.
Set - Brass Cap on N. side of Corner tree Mkd: T31S R9W
 County Surveyor's Office, 1967 ¼ S 33 | S 34
New BTs- 7" Tan Oak S.21°E., 9.5 ft.. mkd. ¼ S34 CS BT.
 12" Laurel S.84°W., 15.8 ft. mkd. ¼ S33 CS BT.

Fd. Ok by D. Edwards, Jan. 2003 - C.S. File 65/46-1