

TOWNSHIP 31 RANGE 09 POINT IDENTIFIER # 400540

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 9 & 10

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GL0 survey by W.H. Byars under contract #727, dated December 20, 1900 - (DCSO records Vol. 19 Page(s) 8209)

Set stone 24x20x10" 18" in ground and marked ¼ on W side for the ¼ sec. cor. from which
 A fir, 24" dia., bears N.54°E., 20 lks., mkd: S10 ¼ S BT.
 A fir, 8" dia., bears S.55°W., 43 lks., mkd: S9 ¼ S BT.

Clifford A. Stephens - For: Coos Head Timber Co. Dec. 1959/Jan. 1961 - M20-16

Find stone mkd: ¼ on face for ¼ corner & new fir post.
Set - ¾" IP along side of post from which:
 8" W. Fir bears S.39°W., 28.0 ft. (scribing on face visible)
 26" Fir bears N.54°E., 13.2 ft.

Douglas Co. Surveyors Office - John M. Powell - Frank Jones & C. Stone - Feb/March 1967 - C.S. File 54/32-22

Found - Corner stone mkd: "¼" and ¾" IP. (1961)
 24" fir stump N.26°E., 13.2 (rec. N.54°E.) scribing "BT"
 8" Fir stob S.86½°W., (rec. S.55°W.) 28.4 ft. scribing "BT"
Set - Brass cap at cor. mkd: County Surveyors T31S R9W Office 1967 ¼ S 9|S 10
New BTs- 14" D.Fir N.39°E., 42.8 ft. mkd: ¼ S20 CS BT.
 8" W.Fir N.19°W., 19.3 ft. mkd: ¼ S9 CS BT.
Note - This corner lies 75 ft. east of a jeep road.

Carl Sweeden - For: Superior Lumber Co - Jan. 2003 - M 141-39

Found - 2½" BC up 1.0' W/¾" I.Pipe along side
 24" D.Fir BT stump, N.26°E., 13.2'
 8" D.Fir stob in SW now gone
 14" D.Fir BT, N.39°E., 42.8' is stump laying over, tie to root hole
New - 8" W.Fir BT now 23" N.19°W. 19.3', crooked, scar vis
 8" D.Fir BT, S.52°E. 12.95' scribed "E¼ S9 BT" & tag
 8" D.Fir BT, S.45°E. 8.77' scribed "W¼ S10 BT" & tag