

TOWNSHIP 31 RANGE 09 POINT IDENTIFIER # 421100

PRIMARY CORNER DESCRIPTION Sec. Cor. for 3 & 4 only, T32-9

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

GLO Resurvey by Fred Mensch and Gerald A. Sorrels, Surveyors under Special Instructions, Group #35, dated Dec. 22, 1916 - (DCSO records Vol. 29 Page(s) 12190-91)

-----  
Set an iron post, 3 ft. long, 2" dia., 24" in the ground, for cor. of secs. 3 and 4, with brass cap mkd:

S 4	S 3
T32S	R9W
1917	

from which

A Fir 20" dia., bears S.70°E., 44 lks. dist. mkd. T32S R9W  
S3 BT

A Fir 20" dia., bears S.81°W., 84 lks. dist. mkd. T32S  
R9W S4 BT

Douglas Co. Surveyors Office - John M. Powell, and crew - March 1967 - C.S. File 54/32-38

-----  
Found - 1917 GLO brass cap, properly marked.  
20" D.Fir, now stump washed out, S.81°W., 55.4 ft.  
20" D.Fir, now snag, S.70°E., 29.0 ft., shows good scar.

New BTs- 5" D.Fir S.45°W., 5.6 ft. mkd. S 4 CS BT.  
8" D.Fir N.37°W., 37.6 ft. mkd. T31S R9W S34 CS BT.  
No other trees available.

This corner lies West of A.P. (old cor. 3 & 4) 141.2 ft.

Tony Hostetter - For: Plum Creek Co. - Jan. 22, 2009 - C.S. File 65/66-16

-----  
Found - 1917 GLO brass cap as described by Mensch & Sorrels (Vol. 29, Pgs. 12190-91)

8" Fir, BLM tag, no other marks, BT marked by Powell in 1967 bears N.37°W., 37.6 ft. to center.

New BTs- 12" fir scribed "S3 NW BT" BT tag, bears N.27°E., 3.9 ft to 20D spike placed in root collar below scribing.

4" fir, scribed "S4 NE BT" BT tag, bears S.73°W., 2.3 ft. to 20D spike placed in root collar below scribing.

16" fir, scribed "S33 SW BT" BT tag, bears N.37°W., 37.6 ft. to 20D spike placed in root collar below scribing.

continued next page

TOWNSHIP 31 RANGE 09 POINT IDENTIFIER # 421100

PRIMARY CORNER DESCRIPTION Sec. Cor. for 3 & 4 only, T32-9

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

BLM dependent resurvey by Kevin G Mulder, Cadastral Surveyor, under Group No. 2862; Surveyed Nov./Dec. 2016 - (DCS0 records Vol. 59 Page(s) 23584-5)

-----  
The cor. of secs. 3 & 4 only, T32S R9W perpetuated by the Douglas County Surveyor's Office in 1967, and further perpetuated by Hostetter, in 2009, under CS 65/66-16; monumented with an iron post, 2" dia., firmly set, projecting 4" above the ground, with brass cap (properly) mkd. from which the remains of a bearing tree mkd. by Mensch and Sorrels in 1917

A broken off and rotted fir stump, size indeterminate, bears S.70°E., 29.0 ft., no marks visible.  
and the remains of a BT mkd by the Douglas Co Surveyor's Office

A sawed fir stump, 28" dia., 7 ft. tall, bears N.39°W., 37.7 ft., with a double healed blaze.

and the remains of bearing trees mkd. by Hostetter

A sawed fir stump, 10" dia., 8 ft. tall, bears N.27°E., 4.5 ft., with scribe marks S4 BT visible on partially healed blaze and a spike in the face.

A fir, 12" dia., bears S.74½°W., 2.4 ft., with a healed blaze.

A sawed fir stump, 17" dia., 9 ft. tall, bears N.11°W., 19.5 ft., with scribe marks S4 BT visible on partially healed blaze and a spike in the face.

and a new bearing tree

A fir, 12" dia., bears S.31½°E., 26.2 ft., mkd. T32S R9W S3 BT.

Each new BT has a 2½"x ¼" magnetic nail (Mag Nail) driven at the base right side-center.