

TOWNSHIP 31 RANGE 09 POINT IDENTIFIER # 500500

PRIMARY CORNER DESCRIPTION Cor Secs 10, 11, 14 & 15

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GL0 survey by W.H. Byars under contract #727, dated December 20, 1900 - (DCSO records Vol. 19 Page(s) 8197)

Set a yew post 4 ft. long, 4" sq., 24" in the ground for the corner to Secs. 10, 11, 14, & 15, marked T31S S11 on NE, R9W S14 on SE, S15 on SW and S10 on the NW face. also 4 notches on the S and 2 notches on E edges, from which
A yew, 8" dia. bears N.68°E., 22 lks. mkd: T31S R9W S11 BT
A fir, 8" dia. bears S.35°E., 24 lks. mkd: T31S R9W S14 BT
A fir, 8" dia. bears S.32°W., 41 lks. mkd: T31S R9W S15 BT
A fir, 10" dia. bears N.85°W. 44 lks. mkd: T31S R9W S10 BT

Douglas Co. Surveyors Office - John M. Powell - Frank Jones & C. Stone - Feb./March 1967 - C.S. File 54/32-9

Found - 8", now 10" Yew, Rotten, N.68°E., 14.5 ft., scribe visible.
8" D.Fir, now down., S.35°E., 15.8 ft., scribe visible.
Do not find SW BT.
10" D.Fir, now stump, N.85°W. 29.0 ft.
Set - Brass Cap at Cor. mkd: County Surveyors T31S R9W
OFFICE S 10 | S 11
1967 S 15 | S 14
New BTs- 8" Hemlock S.28°W., 24.3 ft. Mkd. T31S R9W S15 CS BT
21" Cedar S.50°E., 35.0 ft. mkd. T31S R9W S14 CS BT.
18" D.Fir N.56½°W. 39.9 ft. Mkd. T31S R9W S10 CS BT.
11" Yew N.79°E., 14.5 ft. Mkd. T31S R9W S11 CS BT.

FD. ok by C. Sweeden, Set steel post 1.0' west, Jan. 2003 - M141-39

Fd. Ok by T. Hostetter, 9/2009 - M160-4