

TOWNSHIP 31 RANGE 09 POINT IDENTIFIER # 500600

PRIMARY CORNER DESCRIPTION Cor. Secs 2, 3, 10, & 11

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by W.H. Byars under contract #727, dated December 20, 1900 - (DCSO records Vol. 19 Page(s) 8199)

Set a Cedar post, 4' long, 4" sq. 24" in the ground for cor. of Secs. 2, 3, 10 and 11, marked T31S S2 on NE, R9W S11 on SE, S10 on SW and S3 on NW faces, with 5 notches on S and 2 notches on E edges, from which
A fir, 24" dia. bears N.12°E., 51 lks. mkd: T31S R9W S2 BT
A fir, 18" dia. bears S.32°E. 27 lks. mkd: T31S R9W S11 BT
A fir, 16" dia. bears S.26°W. 37 lks. mkd: T31S R9W S10 BT
A fir, 18" dia. bears N.40°W. 137 lks. mkd: T31S R9W S3 BT

Douglas Co. Surveyors Office - John M. Powell - Frank Jones & D. West - Feb./March 1967 - C.S. File 54/32-7

Found - Orig. D.Fir, now 26" N.12°E., 33.7 ft., shows good scars but burnt face, faint scribe marks visible.
Orig. 18" now 20" D.Fir S.32°E., 17.8 ft., scribe visible.
Orig. 16" D.Fir now stob, S.26°W., 24.4 ft., shows good scar.
Orig. 18" now 28" D.Fir N.40°W., 90.4 ft., shows good scars.

Set - Brass cap at cor. mkd: COUNTY SURVEYORS T31S R9W
OFFICE S 3 | S 2
1967 S 10 | S 11

New BT - 36" D.Fir S.5°W., 25.1 ft., mkd: T31S R9W S10 CS BT.

Carl Sweeden - For: Superior Lumber Co - Jan. 2003 - M 141-39

Found - 2½" BC up 1.10' (1967)
18" now 13" D.Fir BT stob 10' tall S.32°E. 16.5' w/ open face, some scribe vis. No bark
16" now 15" D.Fir BT stob 10'-12' tall S.26°W., 23.4' no bark, scar visible
28" D.Fir BT now uprooted stump N.40°W. 90.4' to roothole.
36" now 39" D.Fir uprooted stump, S.5°W., 25.1' to roothole

New - 14" Hemlock BT, N.31°W. 10.97' scribed "SE S3 BT" & tag
7" D.Fir BT, N.24°E., 5.78', scribed "SW S2 BT" & tag.

Fd. Ok by Jerry Estabrook, 6/2005 - M148-32

continued next page

TOWNSHIP 31 RANGE 09 POINT IDENTIFIER # 500600

PRIMARY CORNER DESCRIPTION Cor Secs 2, 3, 10, & 11

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

BLM dependent resurvey by Francis J. Simon, Cadastral Surveyor under Group #2325, surveyed July/Nov. 2010 - (DCSO records Vol. 57 Page(s) 22759)

The cor. of secs. 2, 3, 10, & 11, perpetuated by the Douglas County Surveyor's Office, in 1967, and further perpetuated by Sweeden, in 2003; monumented with an iron post, 1½" dia., firmly set, projecting 13" above the ground, with brass cap (properly) mkd.

from which the remains of the original bearing trees
A root hole, bears N.12°E., 33.7 ft., with down fir alongside, size indeterminate, no marks visible.

A broken off fir snag, 13" dia., bears S.32°E., 16.4 ft., with scribe marks S11 visible on open blaze. (Record, 17.8 ft.)

A fir stump, 14" dia., bears S.26°W., 22.8 ft., with scribe marks 31S visible on open blaze. (Rec 24.4 ft.)
and the remains of a BT mkd by Douglas Co Surveyors Office

A stump hole, bears S.10°W., 24.9 ft., with down fir alongside, size indeterminate, no marks visible.
and bearing trees mkd. by Sweeden

A fir, 9" dia., bears N.31½°E., 5.8 ft., with a healed blaze.

A hemlock, 16" dia., bears N.28°W., 11.0 ft., with scribe marks SECORS3BT visible on partially healed blaze.
and new bearing trees

A fir, 11" dia., bears S.44½°E., 35.9 ft., mkd. T31S R9W S11 BT.

A fir, 6" dia., bears S.19¼°W., 5.5 ft., mkd. T31S R9W S10 BT.

(NAD 1983 (CORS 96))

Latitude: 42°53'48.71"N. Longitude: 123°44'30.13"W.