

TOWNSHIP 31 RANGE 09 POINT IDENTIFIER # 540440

PRIMARY CORNER DESCRIPTION Center 1/4 Cor Sec 14

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Tony Hostetter - For: Roseburg Resources Co. & Plum Creek -
Sept. 2009 - M160-4

Set - 5/8"x30"" rebar w/plastic cap marked "HOSTETTER LS
1975" from which:
6" fir, scribed "S14 1/16 BT", bears; N.13°17'E., 6.6
ft to spike.
24" fir, scribed "S14 1/16 BT", bears; N.54°59.E., 47.1
ft to spike.
5" cedar, scribed "S14 1/16 BT", bears; S.23°21'E., 5.1
ft to spike.
12" fir, scribed "S14 1/16 BT", bears; S.5°23'W., 66.0
ft to spike.

Douglas Co. Surveyor's Office - Crew: Stephen J. Flause and
Jeff Lorsung - 1-30-2025 - C.S. File 67/59-56

Found - 5/8" I.Rod with plastic cap marked Hostetter LS 1975
10" D.Fir N.13°17'E. 6.6ft fully healed single blaze
8" I.Cedar S.23°21'E. 5.1ft partially healed single
blaze all scribes visible.
14" D.Fir S.5°23'W. 66.0ft fully healed single blaze
Sawn, rotted 21"x6½' fir stump N.54°59'E. 47.5ft
Face rotted off. 6" spike nail loose on ground.
Note: All distances to head of 6" spike into bottom
of scribed faces were measured.
Notes - Mon is on moderate N.E. slope 55' N. of gravel road
Compass decl. 14½°E.
GIS Position Good - checked with handheld
N 42.87512 W 123.73152