

PRIMARY CORNER DESCRIPTION Cor. Secs. 5, 6, 7, & 8

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by Charles L. Campbell, Deputy Surveyor, under Contract #747 dated May 5, 1902 - (DCSO records Vol. 20 Page(s) 8348

Set an ironstone 15x12x8", 12" in the ground for cor. of secs. 5, 6, 7, & 8 mkd with 5 notches on S & E edges, from which
A fir, 30" dia., bears S.8°E., 71 lks. mkd: T32S R2W S8 BT
A fir, 12" dia. bears S.24½°W., 45 lks mkd: T32S R2W S7 BT
No other trees in limits. Raise mound of stone, 2 ft. base, 1½ ft. high, W of cor. Pits impracticable.

Douglas Co. Surveyors Office - Larry E. Monrean, Deputy - Randall Smith & Stephen J. Flause, Witnesses - Sept. 5, 1985 - C.S. File 62/29-16

Found - Stone measuring 14x9x7" (Record 15x12x8) lying slightly recessed in the ground (not firmly set.) No notches or marks distinguishable.
A fir, 30" now 53" dia. with well healed blaze bears S.8°E., 43.9 ft. (Rec. 46.9 ft. checks when measured along ground slope) We open blaze and find scribing "S 8".
Record 12" now 27" fir with well healed single blaze bears S.24½°W., 27.6 ft. (Rec. 29.7 ft. checks when measured along ground slope.) We open blaze and find fragmentary scribe marks 4 to 5" from center of tree.
Set - 1"x30" iron pipe with brass cap 24" deep at position of found stone. Cap is marked "Douglas County Surveyor T32S R2W S6 S5 S7 S8 1985". Stone is placed at SSE edge of brass cap monument.
New BTs- 20" W.Fir double blazed and scribed "T32S R2W S6 CS BT" bears N.16°W., 34.5 ft.
21" D.Fir double blazed and scribed "T32S R2W S5 CS BT" bears N.33½°E., 26.0 ft.
Monument lies approx. 200 ft. ± South from the intersection of USFS Roads 32 and 3200-260.