

TOWNSHIP 32 RANGE 02 POINT IDENTIFIER # 500500

PRIMARY CORNER DESCRIPTION Cor. Secs. 10, 11, 14, & 15

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

GLO survey by Charles L. Campbell, Deputy Surveyor, under Contract #747 dated May 5, 1902 - (DCSO records Vol. 20 Page(s) 8311

-----  
Set a fir post, 4 ft. long, 3" sq., 24" in the ground for cor. to secs. 10, 11, 14, & 15, marked T32S S 11 on NE, R2W S 14 on SE, S 15 on SW, and S 10 on NW faces, with 4 notches on S & 2 notches on E edges; from which  
A fir, 12" dia. bears N.46°E., 23 lks mkd: T32S R2W S11 BT  
A fir, 12" dia., bears S.32°E., 115 lks., mkd: T32S R2W S14 BT.  
A fir, 40" dia., bears S.10½°W., 13 lks., mkd: T32S R2W S15 BT.  
A fir, 24" dia. bears N.40°W., 34 lks mkd: T32S R2W S10 BT

Douglas Co. Surveyors Office - Vernon "Ray" Tracy - Vincent Perron - 8/4/1970 - C.S. File 54/117-9

-----  
Found - Orig. 40", now 50" Fir, alive, S.10½°W. 8.6 ft., blaze badly burned, scribe "S 1" visible.  
Orig. 24" Fir N.40°W. 22.4 ft., only decayed remains found, no scribe.  
No trace other Orig. BTs due to fire many years ago.  
Set - Brass Cap at Cor. Mkd: County Surveyors, T32S R2W  
Office S 10 | S 11  
1970 S 15 | S 14  
New BTs- 12" W.Fir S.86°W. 24.5 ft. mkd: "T32S R2W S15 CS BT"  
15" W.Fir N.65°W. 42.1 ft. mkd: "T32S R2W S10 CS BT"  
40" Pine N.42°E. 24.5 ft. mkd: T32S R2W S11 CS BT".  
7" D.Fir S.45°E. 38.5 ft. mkd: T32S R2W S14 CS BT".  
This corner lies on flat in extremely dense reproduction & Rhododendron Brush.