

PRIMARY CORNER DESCRIPTION Cor. Secs 13, 14, 23, & 24

Alias	Description

GLO survey by Charles L Campbell, Deputy Surveyor, under Contract #747 dated May 5, 1902 - (DCSO record Vol. 19 Page(s) 8297

Set an ironstone 24x12x10", 18" in the ground for cor. of secs. 13, 14, 23, & 24 mkd with 3 notches on S & 1 notch on E edges, from which

- A fir, 34" dia., bears N.73½°E., 113 lks., mkd: T32S R2W S13 BT.
- A fir, 40" dia. bears S.23°E., 54 lks mkd: T32S R2W S24 BT
- A fir, 28" dia. bears S.33°W., 64 lks mkd: T32S R2W S23 BT
- A fir, 60" dia. bears N.4½°W., 70 lks mkd: T32S R2W S14 BT

Douglas Co. Surveyors Office - James W. Byron, Deputy - Mike Darby - Wm. Stoffel - March 1963 - C.S. File 53/15-2

Found - Orig. 40" now 40" partly rotted stump, S.23°E., 35.6 ft. No scribing.
Orig. 28" now 40" Fir S.33°W., 42.2 ft., shows scribing.
Orig. NW BT down. Orig. NE BT not found.
Corner stone not found - in cat. road.

Set Brass cap at cor. mkd: COUNTY SURVEYORS S14|S13 T32S R2W
OFFICE 1963 S23|S24

New BTs- 8" Fir bears N.46°W., 45.4 ft. scribed S14 T32S R2W CS BT.
20" Fir bears N.25°W., 84.0 ft. scribed S14 T32S R2W CS BT.
No trees near to NE & SE.

Douglas Co. Surveyors Office - M. Lenora Lading - K. Cheney - Pete L. Earle - June 29, 1976 - C.S. File 59/15-24

Found - A small mound of stone with a 1963 County Surveyors Brass cap bent and on ground.
An orig. 28" now 47" Fir snag bears S.33°W., 42.2 ft. with "R2W" visible on open blaze.
An 8" now 16" fir bears N.46°W., 45.4 ft. Tree alive with well healed blaze.
A 20" now 24" fir bears N.25°W., 84.0 ft. Tree alive with healing blaze.

Set at true corner point: A new 1"x36" IP w/brass cap stamped
DOUGLAS CO. SURVEYOR T32S R2W
1976 S 14|S 13
S 23|S 24

continued next page

TOWNSHIP 32 RANGE 02 POINT IDENTIFIER # 600400

PRIMARY CORNER DESCRIPTION Cor. Secs. 13, 14, 23, & 24

Alias	Description
Alias	Description
Alias	Description
Alias	Description

<p>Note - Corner falls in edge of old dirt road. Placed Brass cap flush with ground. Placed sign post 4 ft. south of corner.</p> <p>New - A 8" Fir bears S.34°E., 26.0 ft. with "T32S R2W S24 CS BT" in double blaze.</p>
<p>Glenn S. Baughman - For: USFS - Dec. 1976 - M56-69; M56-70; M56-68</p> <p>-----</p> <p>Found - 1963 Doug. Co. Surveyors brass cap. 16" Fir, bears N.46°W., 45.4 ft. 24" Fir bears N.25°W., 84.0 ft. 8" Fir bears S.34°E., 26.0 ft.</p> <p>New BT - 26" W.Fir bears S.44°W., 72.0 ft. scribed T32S R2W S23 BT. No trees to the NE.</p>
<p>Loyd R. Moffit, LS 944 - For: USFS - June 1985 - C.S. File 63/8-11&19</p> <p>-----</p> <p>Found - 2½" brass cap on a 1½" iron pipe. 16" fir bears N.46°W., 46.4 ft. scar visible. 14" fir bears S.34°E., 26.0 ft. scar visible. 24" fir bears S.44°W., 72.0 ft. scar visible.</p> <p>New BT - 6" fir bears N.12°E., 23.5 ft. mkd: T32S R2W S13 BT. Addt'l info added 6/7/85)</p> <p>Found - 27" fir bears N.25°W., 84.0 ft. scar visible.</p>