

PRIMARY CORNER DESCRIPTION C C for Secs. 18 & 19 only

Alias	Description
Alias	Description
Alias	Description
Alias	Description

GLO survey by Fred Mensch under special Instructions dated August 20, 1912 (DCSO records Vol. 20 Page(s) 8448)

Intersect the E. bdy. of T32S R4W, 3.47 chs. S.0°34'W. of the cor. of secs. 13 and 24.

At the point of intersection, I set a granite stone 10x12x8 ins., 15" in the ground, for closing cor. of secs. 18 and 19, marked CC on E.; with 3 grooves on N. and S. faces; from which

A Fir 24" dia., bears N.24°E., 77 lks. dist., mkd. T32S R3W S18 BT.

A Fir 48" dia., bears S.47°E., 53 lks. dist., mkd. T32S R3W S19 BT.

GLO resurvey by Hans W. Thielsen, under Group #'s 350 & 422, Surveyed, May/June 1959 - (DCSO records Vol. 30 Page(s) 12774)

The closing cor. of secs. 18 and 19, T32S R3W, monumented by Mensch with a granite stone 20x12x8 ins., firmly set, marked CC on E. face, with 3 grooves on N. and S. faces, from which the remaining original bearing tree:

A Fir 54" dia., bears S.47°E., 53 lks. dist., mkd. with a healed face.

At the corner point

Set an iron post, 28 ins. long, 2 1/2 ins. dia., 20 ins. in the ground, with brass cap marked

T32S T32S
S 24 $\frac{S 18}{S 19}$ CC
R4W R3W
1959

from which a new bearing tree

A Chinquapin 5" dia., bears N.29°E., 39 lks. dist., mkd. T32S R3W S18 CC BT.

Deposit granite stone alongside iron post.

Survey by Lorne V. Swearingen - For: Southern Oregon Plywood - Oct. 30, 1969 - C.S. File 55/85

Found - 1959 Cadastral brass cap, properly marked.

The bearing tree for Sec. 18 was in good shape and the BT for Sec. 19 was fell with stump remaining on a very high cut bank of new road construction.

Because of the very high cut bank and the inaccessability of reasonably close bearing trees, and the fact that there will be a possibility of a future timber sale in Sec. 19, I scribed the following bearing tree:

7" Hemlock S.38°W., 21.1 ft. mkd. T32S R4W S24