

TOWNSHIP 32 RANGE 03 POINT IDENTIFIER # 300400

PRIMARY CORNER DESCRIPTION CC Secs. 20 & 21, North

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by Fred Mensch, Deputy Surveyor- Under special instructions dated Aug. 20, 1912 - (DCSO records Vol. 20 Page(s) 8440)

Intersect S. bdy of sec. 16, N.87°27'E., 11.00 chs. from the cor. of secs. 16 & 17.
At the point of intersection, I
Set a serpentine stone 14x8x6", 10" in the ground for closing cor. of secs. 20 & 21 mkd C C on S, with 4 grooves on E face, from which
A yew, 6" dia. bears S.88°E., 50 lks. mkd: T32S R3W S21 BT
A fir, 40" dia. bears S.18°W., 73 lks mkd: T32S R3W S20 BT

Douglas Co. Surveyors Office - George J. Wenderoth, Deputy - 1945 - C.S. File 38/41A

Find stone for NE Cor. Sec. 20
40" Fir S.43°E., 37.9 - as this corner (stone & BT) will be destroyed by new road I mark new BTs:
5" Yew bearing S.73°30'E., 68.4 ft.
16" Hemlock bearing S.80°45'W., 111.5 ft.
added info about fd stone & BT 6/14/2011 JC DCSO

Douglas Co. Surveyors Office - John M. Powell - Frank Jones & W. Penley - July 1969 - C.S. File 54/91-15

Found - 5" now 6" Yew S.73½°E., 68.4 ft scribe visible. 1945
16" now 18" hemlock S.80¾°W., 111.5 ft. shows good scar.
Set - Brass cap at CC mkd: COUNTY SURVEYORS T32S R7W
OFFICE S 16
1969 CC S 20 | S 21
New BT - 7" D.Fir N.8°E., 7.3 ft. mkd: T32S R3W S16 CS BT.
This corner lies on west side of old abandon logging road, Dismal Creek Rd.

Malcolm Clark, Chickering Green/Empire INC - For: USFS - 3/21/1980 - M82-68 & C.S. File 58/227(N)

Found - 1969 County brass cap
10" D.Fir N.14°E., 7.0 ft.
New BTs- 12" D.Fir S.51°E., 17.7 ft. scribed "T32S R3W S21 CC BT"
12" D.Fir S.13°W., 69.0 ft. scribed "T32S R3W S20 CC BT"

continued next page

PRIMARY CORNER DESCRIPTION CC Secs. 20 & 21, North

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Leonard Herzstein, USFS - Aug/Sept 2007 - M154-54 & C.S. 65/61-12

Found - 1½" outside dia. iron pipe, firmly set, projecting 8" above old roadbed, with a 2½" dia brass cap (properly) marked

From which the BTs marked by Wenderoth in 1945:

7" yew in Dismal Creek logjam, with USFS tags.

20" hemlock, bears S.79°W., 100.5 ft, with healed double blaze (rec. 1945, S.80°45'W., 111.5 ft; 1969, S. 80¾°W., 111.5 ft).

And bearing tree marked by Powell in 1969:

20" D.Fir, bears N.14°15'E., 7.9 ft, with healed double blaze (rec. 1969, N.8°E., 7.3 ft; 1975, N.8°E., 7.1 ft; 1980, N.14°E., 7.0 ft). This tree is on the old roadbed.

And bearing trees marked by Clark in 1980:

24" D.Fir, S.52°15'E., 17.9 ft, with healed double blaze (rec. S.51°E., 17.7 ft). This tree is on the old roadbed.

SW bearing tree has been washed away.

I bury the monument, a 32"x1" I.D. iron pipe, flared at the base, 32" in the ground. Per the BLM Manual, I add marks "AM" for Amended Monument & marks "LS 2150""2007" to the brass cap.

THE TRUE CLOSING CORNER OF SECTIONS 20 & 21

Old corner bears S.0°20'13"E., 16.22 ft. from true corner.

At the true intersection with the south line of section 16, I set a 2½" inside dia. iron pipe, 32" long, set 26" in the ground, with a 3 ft dia mound of stone to the cap. A 3¼" attached brass cap, pre-stamped "U.S.DEPT. OF AGRICULTURE FOREST SERVICE""UNLAWFUL TO DISTURB CADASTRAL SURVEY" is marked T32S R3W S16/S20 S21 CC LS 2150 2007.

From which existing bearing trees:

24" D.fir, bears S.27°45' E., 30.7 ft, marked by Clark in 1980 with healed double blaze. This tree is on the old roadbed and the blaze faces N.52°W.

20" hemlock, bears S.70°15'W., 104.7 ft, marked by Wenderoth in 1945 with healed double blaze.

And new accessories I mark:

3/8" rebar, 12" long, bears N.84°59'E., 26.52 ft, driven flush with the old roadbed with red plastic cap attached marked "CP USFS"

6 ft alum post, bears S.87°E, 3.1 ft, driven 1.5 ft in the road ditch with Forest Service signs #54-2 "Property" & #54-9 "Land Survey Monument" attached

continued next page

TOWNSHIP 32 RANGE 03 POINT IDENTIFIER # 300400

PRIMARY CORNER DESCRIPTION CC Secs. 20 & 21, North

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

9" W.Fir, bears S.21°45'W. , 32.1 ft, scribed "T32SR3W S20 CC BT" on a single blaze. This tree is in the road ditch.

The corner falls on the cut bank of the old Dismal Creek road, approximately 6 ft from the west edge of the road. Bearings for this establishment are from my traverse, rounded to the nearest 15 minutes, except for the rebar with red plastic cap which is rounded to the nearest minute. Bearing trees are measured to the center of the root crown. Tree diameters are at breast height. New bearing trees have a 34 brass washer, stamped "LS 2150", nailed to the "BT" portion of the blaze.