

TOWNSHIP 32 RANGE 03 POINT IDENTIFIER # 426400

PRIMARY CORNER DESCRIPTION South 1/4 Cor. Sec. 15; only

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by W.H. Byars under contract #152, dated June 3, 1871 - (DCSO records Vol. 20 Page(s) 8367-8)

-----  
Set ¼ sec. post, from which  
A fir, 12" dia., bears N.35°E., 24 lks.  
A fir, 36" dia., bears S.35°W., 24 lks.

GLO survey by Fred Mensch, Deputy Surveyor- Under special instructions dated Aug. 20, 1912 - (DCSO records Vol. 20 Page(s) 8404)

-----  
Intersect the point for cor. of secs. 15 and 22, located by reference to the bearing trees. All other traces of cor. have disappeared. I reestablish this cor. in its original position for sec. 15 only as follows:  
Set a basalt stone, 15x10x6" 10" in the ground, for sec. cor., for sec. 15 only, marked ¼ on N. face; from which  
A fir, 24" dia., bears N.37°E., 25 lks., mkd: ¼ S15 BT.  
A fir, 20" dia., bears N.30°W., 37 lks., mkd: ¼ S15 BT.  
I destroy the marks on the BT S of line.

Douglas Co. Surveyors Office - John M. Powell - Frank Jones & W. Penley - 7/11/1969 - C.S. File 54/91-12

-----  
Found - 15x10x6" stone mkd: "¼" on North face.  
20", now 28" D.Fir, N.30°W. 24.4 ft. shows good scar  
24", now 32" D.Fir, N.37°E. 16.5 ft. shows good scar  
Set Brass Cap at Cor. Mkd: County Surveyors T32S R3W  
Office ¼ S 15  
Bearing Trees OK and Tagged.