

TOWNSHIP 32 RANGE 03 POINT IDENTIFIER # 500440

PRIMARY CORNER DESCRIPTION 1/4 cor. Secs. 14 & 15

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

<p>GL0 survey by W.H. Byars under contract #152, dated June 3, 1871 - (DCSO records Vol. 20 Page(s) 8364)</p> <p>-----</p> <p>Set ¼ sec. post, from which A fir, 30" dia., bears N.60°E., 28 lks. A fir, 8" dia., bears S.70°W., 22 lks.</p>
<p>GL0 survey by Fred Mensch, Deputy Surveyor- Under special instructions dated Aug. 20, 1912 - (DCSO records Vol. 20 Page(s) 8401)</p> <p>-----</p> <p>The point for ¼ sec. cor. located by reference to the SW BT which is a hemlock instead of a fir as given in orig. field notes. All other traces of this cor. have disappeared. I now reestablish this cor. in its orig. position as follows Set a slate stone 15x10x5", 10" in the ground for ¼ sec. cor. mkd. ¼ on West face, from which A hemlock, 10" dia., bears N.25°E., 30 lks., mkd: ¼ S14 BT A hemlock, 12" dia., bears S.70°W., 22 lks., mkd: ¼ S15 BT</p>
<p>J.H. Markham, Jr. - For: M &amp; B Logging Co. - Wit: H.C. Stokes &amp; S.L. Brown - June 26, 1958 - C.S. File 42/378</p> <p>-----</p> <p>Found - 16" Hemlock windfall bears S.70°W. 14.5 ft. OBT fd scribe. At Corner point found Stone mkd: ¼ and Set - 1" x 30" Iron Pipe from which 16" W.Fir bears S.2°E. 13.1 ft. mkd: ¼ S14 T32S R3W BT. 5" Yew bears S.70°W. 38.0 ft. mkd. ¼ S15 BT. 8" Yew bears S.40°W. 56.4 ft. mkd. ¼ S15 R3W BT. Creek bears South 28.0 ft. Road bears North 56.0 ft.</p>
<p>John H. Markham, Jr - For: Stomar Lumber Co. - Wit: J.L. Markham - Aug. 18, 1959 - C.S. File 42/356-12</p> <p>-----</p> <p>Found - 16" W.Fir Stump(logged) bears S.2°E. 13.1 ft. OBT found scribe. All other BTs gone. At Corner point Set 1¼"x36" Truck Axle w/flange up, from which 13" W.Fir bears N.23°W. 151.7 ft. mkd. ¼ S15 BT. 10" Yew bears S.58°E. 142.5 ft. mkd. ¼ S14 T32S BT. 14" W.Fir bears S.49°E. 176.0 ft. mkd. ¼ S14 BT. Corner lies on West edge of Logging Rd &amp; 25 ft North of Creek</p>
<p>continued next page</p>

TOWNSHIP 32 RANGE 03 POINT IDENTIFIER # 500440

PRIMARY CORNER DESCRIPTION 1/4 cor. Secs. 14 & 15

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

Douglas Co. Surveyors Office - John M. Powell - Frank Jones & W. Penley - July 1969 - C.S. File 54/91-39

-----  
Found - No trace of truck axle.  
16" W.Fir, now stump, S.2°E., 13.1 ft scribe visible  
13" W.Fir, now stob, N.23°W. 151.7 ft scribe visible  
14" W.Fir, now snag, S.49°E. 176.0 ft scribe visible  
10", now 11" Yew S.58°E., 142.5 ft. scribe visible  
Set brass cap at cor. mkd: COUNTY SURVEYORS T32S R3W  
OFFICE, 1969 ¼ S15 S14  
New BO - 3/4" I.Rod bears N.53°W., 50.0 ft.  
This corner lies on west side of old logging road.

Leonard Herzstein, USFS & Deputy Douglas Co. Surveyor - Jim Landrum, witness - Oct. 15, 1981 - C.S. File 61/29-20

-----  
Found - 1½" IP firmly set, projecting 12" above ground.  
IP is in old rd. bed & lies above an old log which is 4 ft. above the natural grade. This corner may collapse or erode away in the future.  
BTs - 16" Fir snag bears S.2°E., 13.1 ft to face, w/scribe marks W3R S23T 41S 4/1 visible on partly decayed dbl. blaze.  
11" half-dead Yew bears S.58°E., 142.5 ft. to face, w/scribe marks S23T 41S 4/1 TB visible on partly healed dble. blaze.  
12" W.Fir snag bears S.49°E., 176.0 ft. w/scribe marks 41S 4/1 TB visible on partly healed dble. blaze.  
Note - Marks by Markham are scribed from bottom to top as if left handed  
BO - 3/4" re-bar bears N.53°W., 50.0 ft., buried 2" under ground, with top 6" bent over horizontal with ground.  
Set - I set a steel fence post 1.2 ft., N.53°W. of IR with USFS signs #54-4, & #54-3 attached. IR is on West edge of an old dirt road.  
New BTs- 5" W.Fir bears N.45°E., 44.0 ft., scribed 1/4 S14 CSBT (dbl blaze)  
7" D.Fir bears N.88°W., 7.6 ft., scribed 1/4 S15 CSBT (dbl blaze)  
Note - Corner lies on West side of old dirt rd., 25-ft. North of creek, and 125 ft. South of USFS Rd. #3242.