

TOWNSHIP 32 RANGE 03 POINT IDENTIFIER # 540600

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 2 & 11

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by W.H. Byars under contract #152, dated June 3, 1871 - (DCSO records Vol. 20 Page(s) 8362)

Set ¼ sec. post, from which
A laurel, 5" dia., N.40°W., 15 lks.
A laurel, 10" dia., S.25°E., 21 lks.

Douglas Co. Surveyors Office - Frank Jones & W. Penley - 7/9/1969 - C.S. File 54/91

Reported as not found.
The BTs 5 & 10" laurels in 1871, since that time it has been burnt and has a SW cutting corner. But fd. no trace of BTs.

Bruce Rogers - For: Westland Properties - Aug. 1970 - M40-24

Set by proportionate measurement.
Set - 5/8" iron rod, from which bears:
5" Madrone bears N.48°W., 16 ft.
11" Fir bears S.60°W., 27.7 ft.

Malcolm Clark - For: USFS - April 1980 - M83-54 and C.S. 58/227 (n)

Found - 5/8" rebar, 1970
12" D.Fir bears S.50°00'W., 25.7 ft. (blazed & Healed)
6" Madrone bears N.57°45'W., 15.6 ft. scribing visible.
Set - Alum, pipe, flared at the bottom with an alum. cap stamped: "T32S R3W ¼ S2 S11 1980 RLS 601"