

PRIMARY CORNER DESCRIPTION Sec. Cor. for 18 & 19 only, T32-2

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by Charles L. Campbell, Deputy Surveyor, under Contract #747,, dated May 5,1902 - (DCSO records Vol. 19 Page(s) 8288-89)

Set an ironstone 24x15x8 ins., 18" in ground for cor. of secs. 13, 18, 19 and 24, marked 3 notches on N. and S. edges, from which
A Fir 48" dia., bears S.8°E., 45 lks. mkd. T32S R2W S19 BT
A Fir 44" dia., bears S.14½°W., 57 lks mkd T32S R3W S24 BT
A Cedar 30" dia, bears N.30½°W. 58 lks mkd T32S R3W S13 BT
No other tree in limits.
Mound and pits impracticable.

GLO Survey by Fred Mensch, U.S. Surveyor Under Special Instructions dated Aug. 20, 1912 - (DCSO records Vol. 20 Page(s) 8358)

Intersect the cor. of secs. 18 and 19, T32S R2W, which is a stone, firmly set, marked and witnessed as described by the Surveyor General. As no bearing tree was formerly taken in sec. 18, I re-witness this cor. as follows: From the cor. already set:
A Madrona 20" dia., bears N.46°E., 131 lks. mkd. T32S R2W S18 BT.
A Fir 48" dia., bears S.8°E., 45 lks. dist. mkd. T32S R2W S19 BT.

Survey by Glenn S. Baughman - For: U.S. Forest Service - Aug. 1968 - C.S. File 55/87-2

Found - Ironstone 24x14x8" with 3 notches on N. and S. edges.
Orig. 48" now 58" Fir with open face & scribes in good condition, bears S.8°E., 29.7 ft.

Set 2" x 30" I.P. with brass cap stamped:

T 32 S
24 | S 18 CC
 | S 19
 | R2W
 | 1968
 | OLS 536

From the pipe monument, the orig. BT is:
58" Fir bears S.8°E., 29.7 ft.
New BT - 10" Madrona N.41°E., 51.3 ft. T32S R2W S18 CC BT.

(Note: BLM letter in C.S. File states that they would not call this a "closing" corner.)