

TOWNSHIP 32 RANGE 04 POINT IDENTIFIER # 140600

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 6 and 7

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

GLO survey by W.H. Byars, Deputy Surveyor under contract # 152 survey dated June 3, 1871 (DCSO records Vol. 20 Page(s) 8460)

-----  
Set ¼ sec. post, from which  
A Fir 12" dia., bears N.65°W., 8 lks. dist.  
A Fir 5" dia., bears S.3°E., 5 lks. dist.

C.E. Roberts - July 1910 - Field Book 12, Page 66

-----  
Set Yewood post 4" sq. mkd. ¼ S C.S.  
Fir 5" dia., bears S.26½°W., 14 lks.  
Pine 8" dia., bears N.48¼°W., 74 lks.

G.G. Stewart, Deputy Co. Surveyor - May 1922 -Vol. 3 Page 121 and M 3-32 and C.S. File 45/186

-----  
Set an Iron pipe at location of original stake as pointed out and agreed upon in writing by Robert Payne, B. Neff, H.J. Wilson, K.H. Cooper and G.A. Picket.  
Marked:  
A 12" Cedar S.51½°W., 9.0 ft.  
A 10" Cedar N.7½°W., 178.7 ft.  
No original BTs to be found.

Douglas Co. Surveyors Office - James W. Byron - For: Doug. Co. Road Dept. - Dec. 1956/Feb. 1957 - Road drawer #48, Envelope for Rd. #36

-----  
Found - 1¼" I.P. in N-S fence line.  
The SW BT gone. The N.7½°W. BT, now 36" Cedar, checks for bearing and distance, shows old blaze. I do not open.  
Blaze and scribed:  
10" Pine "¼ S6 CS BT" 21.7 ft. N.25°E.  
20" Cedar "¼ S7 CS BT" S.51°W., 9.7 ft.

BLM resurvey by Larry Evans, Cadastral Surveyor under Group #736, surveyed May/June 1971 (DCSO records Vol. 37 Page(s) 15341)

-----  
The ¼ sec. cor., perpetuated and recorded by Stewart in 1922, from original 1871 corner evidence which is no longer in existence, monumented with an iron pipe 1¼" dia., protruding 4" above the ground, firmly set, from which bearing trees mkd. by Stewart:  
A Cedar 36" dia., bears N.7½°W., 271 lks. with healed double blaze. (Cont. Next Page)

TOWNSHIP 32 RANGE 04 POINT IDENTIFIER # 140600

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 6 and 7

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

A Cedar 26" dia., bears S.51°W., 14½ lks. with healed double blaze. (Rescribed by Byron in 1957) and a bearing tree mkd. by Byron in 1957:

A Ponderosa Pine 17" dia., bears N.22½°E., 33 lks. with healed double blaze.

At the corner point

Set an iron post, 28" long, 2 1/2" dia., 24" in the ground directly over the iron pipe, with brass cap mkd:

T 32 S R 4 W

1     S 6

      /    S 7

      4  1971

From this point, the NE. cor. of a wood frame garage, bears N.59°W., 0.18 chs. dist., dimensions 10 x 15 ft., long side bears S.15°E.

Fd. OK, Wm. Ruppert, August 1984, C.S. File 58/215  
Fd. OK, R. Templin, July 1994 - 1995-0115 A & B  
Fd. BC by Neil Hibbs, 7/2009 - 2009-0043  
Fd. BC by Neil Hibbs, 7/2013 - M165-46

Daniel Baker - For: Weyerhaeuser - 7/2019 - M176-18A-C

-----  
Found - 3¼" BLM brass cap "1971"  
35" P.Pine, N.22°E., 21.7' (rec. = N.25°E. 21.7') to nail side/center-1956 Douglas Co. BT.  
36" Cedar, S.51°W., 10.0' (rec.= S.51°W., 9.7') to nail side/center-1956 Douglas Co. BT.  
47" Cedar, N.7°W., 178.6' (rec. = N.7½°W., 178.7') to nail side/center-M3-32 BT  
NE corner of garage, N.45°W., 12.0' (rec.= N.59°W., 0.18 chs) to bldg. corner-1971 BLM bearing object