

PRIMARY CORNER DESCRIPTION Center 1/4 Cor. for Sec. 5

Alias	Description
_____	_____
_____	_____
_____	_____
_____	_____

<p>Survey by Bruce A. Shaner - For: Aggson and Harrison - June 1963 - RM 1-37</p> <p>-----</p> <p>Set 5/8" x 36" Iron rod, from which A 14" D.Fir bears S.7°W., 27.7 ft. scribed C¼ S5 BT. An 18" D.Fir bears N.47°W., 68.5 ft. scribed C¼ S5 BT.</p>
<p>Bruce A. Shaner - For: G. Hilterbrant - Jan. 1965 - M 22-62</p> <p>-----</p> <p>Reset 5/8" Iron rod from old BTs. 12" D.Fir S.17°W., 23.7 ft. 16" D.Fir N.49°W., 74.3 ft.</p>
<p>Iron Rod Fd. OK, Bruce Rogers, Oct. 1993, 1993-0082 Fd. OK 2 stumps, by G. Lang, Feb. 2000 - M135-61 Fd. 5/8" I.R & 2 BT stumps by R. Wytcherley Nov 2001 - M139-5</p>
<p>BLM dependent resurvey by Kevin G Mulder, Cadastral Surveyor, under Group No. 2627; Surveyed April/May 2013 - (DCSO records Vol. 58 Page(s) 23064-5)</p> <p>-----</p> <p>The center ¼ sec. cor. of sec. 5, established by Shaner, in 1963, and reset to corrected position by Shaner, in 1965, and is accepted as the cor.; monumented with an iron rod, 5/8" dia., firmly set, projecting 2" above the ground, from which bearing trees mkd. by Shaner.</p> <p>A sawed fir stump, 25" dia., bears S.16°W., 23.8 ft., no marks visible.</p> <p>A sawed fir stump, 25" dia., bears N.47¾°W., 75.0 ft., with a healed blaze.</p> <p>At the corner point Set a stainless steel post, 28" long, 2½" dia., 26" in the ground, directly over the iron rod, with brass cap mkd.</p> <p style="text-align: center;">T 32 S R 4 W C ¼ S 5 2013</p> <p>and new bearing trees A fir, 8" dia., bears N.29°E., 21.5 ft., mkd. C ¼ S5 BT. A fir, 6" dia., bears S.56½°E., 18.5 ft., mkd. X at breast height and BT at the base.</p> <p>Each new bearing tree has a 2 1/2 inch x 1/4 inch magnetic nail (Mag Nail) driven at the base on right side center Deposit a magnet in a white plastic case at the base of the stainless steel post.</p>
<p>Fd. ok by R. Brown 1/2015 - M166-31</p>