

TOWNSHIP 32 RANGE 04 POINT IDENTIFIER # 371100

PRIMARY CORNER DESCRIPTION A.P. #1, S. bdy. Sec. 33

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GL0 survey by McKenzie and Eckelson, Deputy Surveyors under Contract #328, dated June 17, 1879 (DCSO records Vol. 20 Page(s) 8465)

Set post for ¼ sec. corners, from which
A Fir 12" dia., S.50°W., 25 lks. dist.
A Fir 6" dia., N.45°W., 6 lks. dist.

GL0 survey by Edward F. Sharp, Deputy Surveyor, under Contract #617, dated June 3, 1893 (DCSO records Vol. 21 Page(s) 8932)

The Standard ¼ sec. cor., which is a post 12" above ground, marked S C ¼ S on N. face, from which
A Fir 12" dia., bears S.50°W., 25 lks. dist. with well defined blazes.
A Fir 6" dia., bears N.45°W., 6 lks. dist., with well defined blazes.

Douglas Co. Surveyors Office, John Powell, W. Penley and J. Heritage, crew - May 14, 1970 - C.S. File 54/114-27

Found - 12" Cedar (Rec. Fir) now 20", S.50°W., 16.5 ft., opened for scribe. (Ring count places age approx. 1885)
6" Fir, down, rotten, N.45°W., 4.0 ft., has very old rotten face, maybe very faint scribe.

Set Brass cap at cor. mkd: County Surveyors Office
Doug. Co.

T32S R4W S 33
T33S S ¼ C
Jack. Co.
1970

New BTs -38" D.Fir N.52°E., 15.6 ft. mkd. S¼ C S33 CS BT.
12" D.Fir N.38°W., 12.7 ft. mkd. S¼ C S33 CS BT.

By pacing, corner hits approx. 9 chains W. of CC S33|S34 and 3 chains East of ridge.

BLM resurvey by Lynn M. Roseberry and Rollin D. Aanrud, Cadastral Surveyors, Under Group #865, surveyed July/Oct. 1975 (DCSO records Vol. 42 Page(s) 16532)

The former standard ¼ sec. cor. of sec. 33, changed to an angle point by Chapman and Nicklin, perpetuated and recorded by the County in 1970, monumented with a mound of stone, 3 ft. base, 1½" high, from which the remains of an original bearing tree: (Cont. Next Page)

TOWNSHIP 32 RANGE 04 POINT IDENTIFIER # 371100

PRIMARY CORNER DESCRIPTION A.P. #1, S. bdy. Sec. 33

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

A Cedar 22" dia., bears S.50°W., 25 lks. dist., with scribe marks 4 SC visible on partially opened double blaze. (Record, Fir)
and bearing trees mkd. by the County
A Fir 34" dia., bears N.52°E., 23½ lks. dist., with scribe marks S ¼ C S33 CS BT visible on pitched over double blaze.
A Fir 12" dia., bears N.38°W., 19 lks. dist., with scribe marks S ¼ C S33 CS BT visible on pitched over double blaze.
At the corner point
Set an iron post, 28 ins. long, 2 1/2 ins. dia., 19 ins. in the ground, and in a mound of stone, 3 ft. base, to top, with brass cap marked
AP 1
T 32 S R 4 W
S 33
1975

Harvey M. Christensen - For: Future Logging Co. & Silver Butte Timber Co. - Feb. 2024 - M183-61

Found - 2.5" BLM BC 1.0' above grade, 1975
BTs - 36" D.Fir N.52°E., 15.5 ft. healed face
18" D.Fir N.38°W., 12.5 ft. healed face
Note - No new trees scribed.
Found - 5/5' steel post, 5 ft. east.