

TOWNSHIP 32 RANGE 04 POINT IDENTIFIER # 400440

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 15 and 16

Alias	Description
_____	_____
_____	_____
_____	_____
_____	_____

GLO survey by Carl S. Nicklin, Deputy Surveyor, under Contract #664, dated May 23, 1896 (DCSO records Vol. 20 Page(s) 8515)

Set a Fir post, 3 ft. long, 4" sq., 24" in the ground for ¼ sec. corner, marked ¼ S. on W. face, from which
A Fir 10" dia., bears S.75°E., 23 lks. mkd. ¼ S BT.
A Fir 12" dia., bears S.27°W., 69 lks. mkd. ¼ S BT.
This ¼ sec. corner is on the SE. slope of spur, 50 ft. above creek.

GLO remonumentation by Hans W. Thielsen, under Group #'s 350 & 422, Surveyed, May/June 1959 - (DCSO records Vol. 30 Page(s) 12798)

The ¼ sec. cor., determined at record bearing and distance from the remaining original bearing tree:
A Fir 20" dia., bears S.27°W., 69 lks. dist., mkd. ¼ S on opened blaze.
At the corner point
Set an iron post, 28" long, 2 1/2" dia., 20" in the ground, with brass cap mkd: ¼
S 16 S 15
T32S R4W
1959
from which new bearing trees
A Fir 18" dia., bears S.47¼°E., 73 lks. mkd. ¼ S15 BT.
A Pine 5" dia., bears S.57 3/4°W., 20 lks. mkd. ¼ S16 BT.

Fd. OK, Greg Lang, July 1995 - M 122-46