

PRIMARY CORNER DESCRIPTION Sec. Cor. for 14, 15, 22 and 23

Alias	Description
Alias	Description
Alias	Description
Alias	Description

GLO survey by Carl S. Nicklin, Deputy Surveyor, under Contract #664, dated May 23, 1896 (DCSO records Vol. 20 Page(s) 8494)

Set a Fir post, 3 ft. long, 4" sq., 24" in the ground for corner of secs. 14, 15, 22 and 23, marked T32S S14 on NE.; R4W S23 on SE.; S22 on SW.; and S15 on NW. faces; with 2 notches on E. and 3 notches on S. edges; from which

A Fir 20" dia., bears N.32°E., 27 lks. dist. mkd. T32S R4W S14 BT.

A Fir 24" dia., bears S.30°E., 57 lks. dist., mkd. T32S R4W S23 BT.

A Fir 24" dia., bears S.52½°W., 17 lks. dist., mkd. T32S R4W S22 BT.

A Fir 24" dia., bears N.45°W., 69 lks. dist., mkd. T32S R4W S15 BT.

This corner is on the S. slope of spur, 300 ft. above last creek.

Survey by Richard L. Templin, Jr. - For: So. Oregon Plywood Corp. - April/May 1956 - C.S. File 42/159

Set a quartz stone 18 x 10 x 7 ins., 10" in the ground and mounded around with smaller quartz stones, from which

26" D.Fir snag bears N.32°E., 17.8 ft. blaze healed.

30" D.Fir bears S.30°E., 37.6 ft. blaze healed.

30" D.Fir snag bears S.51°W., 11.2 ft. blaze healed.

30" D.Fir snag bears N.45°W., 45.6 ft. scribe visible.

Corner located in a recent burn and no green trees available to scribe.

GLO remonumentation by Hans W. Thielsen, under Group #'s 350 & 422, Surveyed, May/June 1959 - (DCSO records Vol. 30 Page(s) 12796)

The Sec. cor., determined at record bearing and distance from each of the original bearing trees:

A Fir snag 30" dia., bears N.32°E., 27 lks. marked with a burned blaze.

A Fir 30" dia., bears S.30°E., 57 lks. marked with a burned blaze.

A Fir snag 26" dia., bears S.52½°W., 17 lks. marked with a burned blaze.

A Fir snag 36" dia., bears N.45°W., 69 lks. marked with a healed blaze.

At the corner point

Set an iron post, 28" long, 2 1/2" dia., 20" in the ground, with brass cap mkd: (Cont. Next Page)

