

TOWNSHIP 32 RANGE 04 POINT IDENTIFIER # 500640

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 2 and 3

Alias	Description
_____	_____
Alias	Description
_____	_____
Alias	Description
_____	_____
Alias	Description
_____	_____

GLO survey by W.H. Byars, Deputy Surveyor under contract # 152 survey dated June 3, 1871 (DCSO records Vol. 20 Page(s) 8457)

Set ¼ sec. post, from which
A Chinquapin 6" dia., bears N.82°E., 44 lks. dist.
A Fir 24" dia., bears West, 32 lks. dist.

Fd. and used in GLO resurvey by Nicklin in 1896, Contract #664 (DCSO records, Vol. 20 Page 8503)

Survey by G. Robert Lecklider - For: Pacific Plywood - July 30, 1959 - M 15-31

Original corner not found.
Set 1/2" Rod.
BTs - 24" Fir S.30°E., 37.2 ft.
32" Fir N.46°W., 39.0 ft.

Found OK by R. Wytcherley, Feb. 2004 - M143-76

Kris DeGroot - For: Silver Butte Timber - 4/2008 - M155-48

Found - 1/2" iron rod by Lecklider in 1959 firmly set, projecting 4" above the ground, at the exact position of the 1/2" iron rod, I set a 1½"x32" iron post, 24" in ground, with 2½" brass cap stamped:
T32S R4W
1/4
S3|S2
2008
PLS 1941

From which bearing trees by Lecklider in 1959:
A 27" fir snag bears N.49°W., 39.1 ft with healed double blaze. Rec. (N.46°W., 39.0 ft.)
A 33" fir bears S.33°15'E., 28.7 ft. with healed double blaze. Rec. (S.30°E., 37.2 ft.)

And a new bearing tree:
A 8" fir bears S.80°45'W., 33.8 ft. scribed "¼ S3 BT"
And new reference monumen7:
A 5/8"x30" iron rod w/plastic cap bears N.80°37'09"E., 25.00 ft.
A 5/8"x30" iron rod w/plastic cap bears N.34°09'44"W., 30.00 ft.

Note the 1/2" iron rod per M15-31 was reset south, 0.2 ft and flush with the ground.