

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 12 and 13

Alias	Description
Alias	Description
Alias	Description
Alias	Description

GLO survey by Carl S. Nicklin, Deputy Surveyor, under Contract #664, dated May 23, 1896 (DCSO records Vol. 20 Page(s) 8489)

Set a Chinquapin post, 3 ft. long, 4" sq., 24" in the ground for 1/4 sec. corner, mkd. 1/4 S on N. face; from which
A Fir 30" dia., bears S.80°W., 39 lks. mkd. 1/4 S BT.
A Chinquapin 6" dia., bears N.21°W., 13 lks. mkd. 1/4 S BT
This cor. is on a hillside sloping E. 75 ft. above bottom of ravine.

GLO remonumentation by Hans W. Thielsen, under Group #'s 350 & 422, Surveyed, May/June 1959 - (DCSO records Vol. 30 Page(s) 12793)

The 1/4 sec. cor., determined at record bearing and distance from the remaining original bearing tree:
A Fir 36" dia., bears S.80°W., 39 lks. mkd. with a healed blaze.
At the corner point
Set an iron post, 28" long, 2 1/2" dia., 20" in the ground, with brass cap mkd:
1/4 S 12
1/4 S 13
T32S R4W
1959
from which a new bearing tree
A Fir 12" dia., bears N.44°E., 97 lks. mkd. 1/4 S12 BT.

Kris DeGroot - For Silver Butte Timber Co. - 8/2010 - M161-16

Lat: 42°47'56.92985"N. Long: 123°07'18.21699"W.
Found - USBLM BCIP by Hans W. Thielsen, Cadastral Surveyor, in 1959 per USBLM Field note Volume OR-R0571, pages 81 & 82, firmly set, projecting 10" above the ground, properly marked:
From which the original BT by Nicklin in 1896:
A 48" Fir bears S.80°W., 25.7 ft, with healed blaze.
And a BT by Thielsen in 1959:
A 24" Fir stump bears N.34°45'E. 64.5 ft (rec. N.44E., 97 lks.) with healed blaze
New BT - A 9" Chinquapin bears N.15°E., 42.2 ft scribed "1/4 S12 BT"
New RMs- A 5/8"x30" iron rod bears N.36°18'36"E., 44.95 ft.
A 5/8"x30" iron rod bears S.15°34'56"W., 20.17 ft.