

TOWNSHIP 32 RANGE 04 POINT IDENTIFIER # 700261

PRIMARY CORNER DESCRIPTION C C for Secs. 19 & 30 only, T32-3

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by Fred Mensch under special Instructions dated August 20, 1912 (DCSO records Vol. 20 Page(s) 8445-6)

Intersect E. bdy of T32S R4W, 19.51 chs. S.1°3'W. of the cor. of secs. 24 and 25.

Point of intersection falls on a granite rock in place, 30x24x12 ins., above ground, on which I cut a cross (X) at exact point for closing cor. of secs. 19 and 30, and mark C; E. with 4 grooves N. and 2 grooves S. of cross, from which
A Fir 36" dia., bears N.89°E., 122 lks. dist., mkd. T32S R3W S19 BT.

A Fir 40" dia., bears S.82°E., 112 lks. dist., mkd. T32S R3W S30 BT.

Douglas Co. Surveyors Office - John M. Powell, Frank Jones, W. Penley, & V Tracy, crew - August 1969 - C.S. File 54/91-57

Found - No trace of corner stone, probably slid downhill.
Orig. 36" Fir, now stob, N.89°E., 80.5 ft. scribe visible.

Orig. 40" Fir now 40" S.82°E., 73.9 ft., burnt face.
Set brass cap at cor. mkd: County Surveyors Office

T 32 S
R 4W CC S25 | S 19 R
 | S 30 3W
 1969

New BTs -12" D.Fir N.44°E., 7.7 ft. mkd. T32S R3W S19 CC CS BT.

12" D.Fir S.59°E., 7.8 ft. mkd. T32S R3W S30 CC CS BT.