

PRIMARY CORNER DESCRIPTION NE Cor. D.A. Levens DLC #38

Alias	Description
Alias	Description
Alias	Description
Alias	Description

DLC Survey by J.A. Burnett, under Contract #75 dated Nov. 22, 1856 ----- Set a post from which A B.Oak 14" dia., bears S.70°W., 77 lks.
W. F. Briggs, Co. Surveyor - For: H.J. Wilson (Levens & Bros. Estate) - July 1900 - Vol. 2 Page 94 ----- Set post as per original BT standing to wit: B.Oak 18" dia., bears S.70°W., 47 lks. (orig. DLC notes said 77 lks. V.L.)
George J. Wenderoth - 1955 - M 7-53 ----- 1" Iron pipe. 10" B.Oak N.49°50'W., 43.0 ft. 8" B.Oak S.21°34'E., 23.7 ft.
Douglas Co. Surveyors Office - Randall W. Smith, Deputy - Stephen J. Flause - 8/23/2000 - C.S. File 66/16-33 ----- Found - 1" I.D. iron pipe 1" below ground in an old down N-S fence line. (1955) 14" now badly rotted B.Oak stump no scribing found, bears S.67½°W., 50.8 ft. (Orig. rec. S.70°W., 50.8 ft.) OBT? 10" now 21" dia., B.Oak with a fully healed single blaze bears N.50°W., 43.0 ft. (1955) 8" now 9" dia., 3 ft. high rotted B.Oak snag, scribing visible "38" bears S.21½°E., 23.7 ft. (1955) New - 14" dia., D.Fir double blazed & scribed "NE DLC 38 CS BT" bears N.16°E., 6.6 ft. 28" dia., D.Fir bark scribed "NE DLC 38 CS BT" bears S.12½°E., 14.4 ft. 9" dia., W.Oak double blazed & scribed "NE DLC 38 CS BT" bears S.40½°W., 48.0 ft. Reset - Fd. I.P. bent & leaning 0.7 east of plumb. Top of I.P. is plumbed over base, now protrudes 3" above ground.