

TOWNSHIP 32 RANGE 05 POINT IDENTIFIER # 100500

PRIMARY CORNER DESCRIPTION Sec. Cor. for 7 & 18; 12 & 13, T32-6

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

Original - W.H. Byars, under contract # 448 survey dated June 13, 1882 (DCSO records Vol. 20 Page(s) 8555)

-----  
Set post, cor. to secs. 7, 12, 13 and 18, from which  
A Fir 10" dia., bears S.11°W., 48 lks.  
A Cedar 12" dia., bears S.24°E., 34 lks.  
A Laurel 9" dia., bears N.34°E., 47 lks.  
A Laurel 8" dia., bears N.30°W., 29 lks.

GL0 survey by Oscar F. Thiel, Deputy Surveyor, under Contract #729, dated Dec. 24, 1900 (DCSO records Vol. 20 Page(s) 8605)

-----  
The Sec. cor., which is gone, and I replace it be setting a Cedar post, 3 ft. long, 4" sq., 24" in the ground, for cor. of secs. 7, 18, 12 and 13, marked T32S S7 on NE.; R5W S18 on SE.; S13 on SW.; and R6W S12 on NW. faces, with 2 notches on N. and 4 notches on S. edges; from which  
A W.Fir 14" dia. bears N.43°W., 30 lks mkd T32S R6W S12 BT  
The other bearing trees as described by the surveyor general.

Douglas Co. Surveyors Office - James Byron, Deputy - Milo Godfrey, S.A. Bilow, crew - June 24, 1959 - C.S. File 49/91-8

-----  
Found - 14" now 16" Fir snag, shows old scar, center burned, no scribing found, bears N.43°W., 19.8 ft. scribed by Thiel.  
Orig. 12" now 24" Cedar S.24°E., 22.4 ft. center burned out, does show good scribing "32 S T".  
Orig. 9" now 18" Laurel N.34°E., 31.0 ft. shows good scribing, "32S R5W S".  
No trace of orig. NW BT.

Set Brass cap at cor. mkd: County Surveyors Office

T 32 S  
R6W S 12 | S 7 R5W  
S 13 | S18  
1959

New BTs -13" Fir bears N.32°E., 39.5 ft. scribed T32S R5W S7 CS BT.  
5" Laurel bears N.52°W., 24.4 ft. scribed S12 CS BT.  
12" R.Fir bears S.58½°E., 51.6 ft. scribed S13 T32S R5W CS BT.  
38" R.Fir bears South 10.0 ft. scribed S13 T32S R6W.

Cor. Fd. and used in BLM survey by Rollin Aanrud, under Group #1018, surveyed June/Aug. 1980 (DCSO records, Vol. 44 Pages 16977-78)

Cont. next pg

TOWNSHIP 32 RANGE 05 POINT IDENTIFIER # 100500

PRIMARY CORNER DESCRIPTION Sec. Cor. for 7 & 18; 12 & 13, T32-6

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Fd. Ok by Lloyd Smith, March 1997 - M124-46  
Found OK by K. Hoffine, Nov. 2002 - M141-34

BLM Dependent resurvey by Arthur R. Rambo, & Francis Simon  
Cadastral Surveyors under Group No. 2143, surveyed May  
2006/Feb. 2007 - (DCSO records, Vol. 55 Page(s) 21672-3)

-----  
The cor. of secs. 7, 12, 13, & 18, on the W. bdy. of the Tp.,  
monumented with an iron post, 1 1/4" dia. firmly set, projecting  
12" above the ground, with brass cap (properly) mkd.

from which remains of original bearing trees  
A madrone, 19" dia., bears N.34°E., 29.9 ft., with open  
rotten face. (Record, 31.0 ft.)

A cedar, 23" dia., bears S.24°E., 22.4 ft., with a healed  
blaze.

and remains of bearing trees mkd. by the Douglas County  
Surveyor's Office, reported by Aanrud

A fir, 22" dia., bears N.32°E., 38.6 ft., with a healed  
double blaze.

A fir, 17" dia., bears S.59 3/4°E., 51.5 ft., with a healed  
double blaze.

A fir stob 8 ft. tall, 50" dia., bears South, 9.9 ft.,  
with fragmentary scribe marks visible on partially  
healed blaze.

A madrone, 10" dia., main stem sawed off at 4 ft. above  
the ground, with live limbs still intact, bears  
N.52°W., 24.4 ft., with a healed double blaze.

and a new bearing tree

A fir, 12" dia., bears S.79°W., 20.1 ft., mkd. T32S R6W  
S13 BT.

Each new bearing tree has a 2 1/2" x 1/4" magnetic nail (Mag Nail)  
driven at the base right side-center, unless otherwise  
described in the corner description