

TOWNSHIP 32 RANGE 05 POINT IDENTIFIER # 340100

PRIMARY CORNER DESCRIPTION 1/4 Cor. Sec. 33; & 4 of T33-5

| | |
|------------------|---|
| Alias <u>(?)</u> | Description <u>A.P. #1 on So. bdy Sec. 33</u> |
| Alias _____ | Description _____ |
| Alias _____ | Description _____ |
| Alias _____ | Description _____ |

Original - Butler Ives and George W. Hyde, under Contract #39, dated January 4, 1854 - (DCSO records Vol. 20 Page(s) 8549)

Set qr. sec. post, from which
A Laurel 5" dia., bears S.60°W., 15 lks.
A Laurel 14" dia., bears N.37°E., 50 lks.

BLM corner remonumentations by Lynn M. Roseberry, Cadastral Surveyor - Under Group #936 and 1000, Surveyed, July 1977/April 1980 - (DCSO records Vol. 42 Page(s) 16642-43)

The Ives and Hyde standard ¼ sec. cor. of secs. 4 and 33, on the N. bdy. of the Tp., determined at record bearing and distance from the only remaining original bearing tree:

A Madrone 22" dia., bears N.37°E., 50 lks. dist., with scribe marks ¼ visible on open and decayed blaze.

This corner now becomes angle point No. 1 of secs. 4 and 33. At the corner point

Set an iron post, 29" long, 2½" dia., 24" in the ground, in a collar of stone, 2 ft. base, to top, with brass cap mkd.

AP 1
T 32 S R 5 W
S 33
S 4
T 33 S
1980

from which new bearing trees

A Fir 13" dia., bears N.84½°E., 122½ lks. dist., mkd. AP1 S33 BT.

A Fir 15" dia., bears S.17½°W., 125 lks. dist., mkd. AP1 S4 BT.

Gregg Neitsch - For: John Hancock Life Insurance Co - 12/2022 - M181-58

Found - 1980 BLM BC/IP
33" dia., D.Fir, with healed blaze, N.83°E., 82.4'
(rec. N.84½°E., 122.5 lks)
33" dia, D.Fir, with healed blaze, S.17°41'W., 82.0'
(rec. S.17½°W., 125 lks)
24" dia., madrone, rotted stump, N.33°48'E., 32.6'
(rec. N.37°E., 50 lks)