

TOWNSHIP 32 RANGE 05 POINT IDENTIFIER # 376100

PRIMARY CORNER DESCRIPTION C C for Secs. 3 & 4 only, T33-5

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

GL0 survey by Edward F Sharp, Deputy Surveyor, under Contract #617, dated June 3, 1893 (DCSO records Vol 21 Pg 8981)

-----  
The C C of Secs. 3 and 4, (which is 5.40 chs. West of cor. to secs.33 and 34, T32S R5W), set a basaltic stone 12 x 10 x 6 ins., 8" in the ground for closing cor., marked C C with 3 notches on E. and W. edges, from which

A Fir 24" dia., bears S.50°E., 210 lks. dist., marked T33S R5W S3 BT.

A Fir 30" dia., bears S.43°W., 100 lks. dist., marked T33S R5W S4 BT.

A Fir 16" dia., bears N.83°E., 170 lks. dist., marked T33S R5W CC S3 and 4 BT.

Survey by Norman D. Price - For: Dollar and Patterson Lumber Co. - July 27-28, 1953 - C.S. File 41/184

-----  
This corner bears South 5½ lks. dist., from the sec. line between 3 and 4 on the South and sec. 33 on the North and is monumented with a basalt stone, 10 x 8 x 5 ins. above ground, firmly set, mkd. CC on S., with 3 grooves on E. and W. faces; from which the orig. BTs:

A D.Fir 24" dia., bears S.48 3/4°E., 210 lks. dist., with old blaze healed.

A D.Fir stub, 30" dia., bears S.43°W., 70½ lks. dist., with old blaze healed.

Against the North side of the stone, Set an iron pipe, 3 ft. long, 2" dia., 28" in the ground, mkd. RS 33 and mark new bearing trees as follows:

A D.Fir 12" dia., bears S.12¼°E., 26 lks. dist., mkd. T33S R5W S3 RS 33 CC BT.

A D.Fir 16" dia., bears S.29°W., 17½ lks. dist., mkd. T33S R5W S4 RS33 CC BT.

FD OK, Sept. 11, 1967, DCSO, John Powell C.S. File 53/52-42

Ronald Quimby - For: Plum Creek Timber Co. - July 2015 - M166-36

-----  
Found - 1½" iron pipe per 1953 survey by PRICE  
84" tall, 8" rotten fir snag S.12°E., 17.2'

96" tall, 8" rotten fir snag S.29°W., 11.6'

New BTs- 31" fir N.33°E., 6.9' scribed "T33S R5W S3 BT"

9" fir S.10°W., 11.7'

6" chinquapin S.47°W., 29.1'

25" fir N.11°W., 38.8'

All three scribed "T33S R5W S4 BT"

cont

TOWNSHIP 32 RANGE 05 POINT IDENTIFIER # 376100

PRIMARY CORNER DESCRIPTION CC for Secs. 3 & 4 only, T33-5

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Ken Hoffine - For: Lone Rock Timber Co - June 2020 - M177-25  
-----

Found - 1½" iron pipe with washer in middle  
27" D.Fir bears N.12°W., 38.2 ft (rec per M166-36 N.11°W., 38.8 ft) visible scribing and BT tag.  
11" D.Fir S.8¼°W., 11.9 ft (Rec per M166-36 S.10°W., 11.7 ft) visible scribing and BT tag  
8" Chinquapin bears S.45¾°W., 28.2 ft (rec per M166-36 S.47°W., 29 1 ft) visible scribing and BT tag.  
Rotten Fir stub bears S.29°W., 11.7 ft (rec per M166-36 S.29°W., 11.6 ft) cut out face  
Rotten Fir stub bears S.12¼°E., 17.1 ft (record per M166-36 S.12°E., 17.2 ft) healed face  
Rotten Fir stub bears S.42¼°W., 47.3 ft (record per C.S. FILE 41/184 S.43°W., 46.53 ft) healed face  
Corner lies on west side of main ridgetop, approx. 88 ft N.28°W. from middle of landing at end of 33-5-4.3 road.

BLM dependent resurvey by Kevin G Mulder, Cadastral Surveyor, under Group No. 3006; Surveyed April 2021/Nov. 2022 - (DCSO records Vol. 59 Page(s) 24134-5) Added 9/10/2024  
-----

The original closing cor. of secs. 3 and 4, perpetuated by Price, in 1953; and subsequently perpetuated by Quimby, in 2015; monumented with an iron pipe, 1½" dia., firmly set, projecting 14" above the ground, with nail and washer on top mkd. RS 33,

from which the remains of an original bearing tree  
A rotted fir snag, size indeterminate, bears S.42¼°W., 47.1 ft., with illegible scribe marks visible on open blaze. (Record, 66.0 ft.)

and bearing trees mkd. by Quimby

A fir, 33" dia., bears N.32°E., 6.9 ft., with scribe marks T33S R5W S3 BT visible on partially healed blaze.

A fir, 11" dia., bears S.8°W., 11.6 ft., with no marks visible on partially healed blaze.

A chinquapin, 8" dia., bears S.45¾°W., 28.6 ft., with scribe marks T33S R5W S4 BT visible on partially healed blaze.

A fir, 27" dia., bears N.11¾°W., 38.1 ft., with no marks visible on partially healed blaze.

Alongside the iron pipe, found the original basalt stone, 12x10x6" loosely set, with chisel marks CC visible on the S. side.

At the corner point  
continued next page

TOWNSHIP 32 RANGE 05 POINT IDENTIFIER # 376100

PRIMARY CORNER DESCRIPTION C C for Secs. 3 & 4 only, T33-5

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

Set a stainless steel post, 28" long, 2½" dia., 22" in the ground, directly over the iron pipe, in a collar of stone, with brass cap mkd.

T 32 S R 5 W  
S33  
S 4 | S 3  
T 33 S R 5 W  
CC  
2021

Bury the original stone alongside the stainless steel post.

Gregg Neitsch - For: John Hancock Life Insurance Co - 12/2022  
- M181-58

-----  
Found - 2021 BLM BC/IP (as of 1/5/2023 not filed)  
35" dia., D.Fir, visible scar, N.31°52'E., 6.8'  
28" dia., D.Fir, visible scar, N.11°58'W., 38.1'  
12" dia., D.Fir, visible scar, S.7°27'W., 12.0'  
20" dia., fir, rotted stump, S.12°29'E., 17.1'  
20" dia., fir, rotted stump, S.28°39'W., 11.8'  
22" dia., fir snag, visible scar, S.42°10'W., 47.6'  
9" dia., Tan Oak, visible scar, S.45°31'W., 28.2'