

PRIMARY CORNER DESCRIPTION So. Sec. Cor. for 33 and 34 only

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Original - Butler Ives and George W. Hyde, under Contract #39, dated January 4, 1854 - (DCSO records Vol. 20 Page(s) 8548)

-----  
Set post cor. of secs. 33, 34, 3 and 4, from which  
A Fir 6" dia., bears N.26°W., 9 lks.  
A Fir 5" dia., bears N.12°E., 10 lks.  
A Fir 7" dia., bears S.66°E., 15 lks.  
A Fir 30" dia., bears S.18°W., 29 lks.

GL0 survey by Edward F. Sharp, Deputy Surveyor, under Contract #617, dated June 3, 1893 (DCSO records Vol. 21 Page(s) 8980-81)

-----  
I determined the sec. cor. 33 and 34 by the SW bearing tree. The post and remaining three bearing trees evidently have been destroyed by fire. I reestablish the cor. to secs. 33 and 34, T32S R5W, by setting a basaltic stone 16 x 10 x 8 ins., 11" in the ground, from which  
A Fir 30" dia., bears S.18°W., 29 lks. dist. with well defined blazes, which I partly cut out to be positive of the cor.  
I relocated the following bearing trees from the cor.  
A Fir 14" dia., bears N.43°30'E., (?) lks. dist. mkd. T32S R5W S34 BT.  
A Fir 14" dia., bears S.53°E., 43 lks. dist. mkd. T33S R5W S3 BT.  
A Fir 14" dia., bears N.25°W., 73 lks. dist., mkd. T32S R5W S33 BT.

Survey by Norman D. Price - For: Dollar and Patterson Lumber Co. - July 27-28, 1953 - C.S. File 41/184

-----  
This corner is monumented with a basalt stone, 8x8x8 ins. above ground, firmly set, mkd. with 3 grooves on E. and W. faces; from which the old bearing trees:  
A D.Fir stub, 24" dia., bears S.53½°E., 43 lks. dist., mkd. T33S R5W S3 BT.  
A D.Fir 52" dia., bears S.16½°W., 30 lks. dist., with old blaze healed.  
A D.Fir stub, 20" dia., bears N.25¼°W., 71 lks. dist., mkd. T32S R5W S33 BT.  
Against N. side of corner stone, Set an iron pipe 3 ft. long, 2" dia., 28" in the ground, mkd. RS33 and mark new bearing trees as follows:  
A D.Fir 6" dia., bears N.40¼°E., 19 lks. dist., mkd. T32S R5W S34 RS33 BT.  
(Cont. Next Page)

TOWNSHIP 32 RANGE 05 POINT IDENTIFIER # 400100

PRIMARY CORNER DESCRIPTION So. Sec. cor. for Secs. 33 & 34, only

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

A D.Fir 6" dia., bears N.8¼°W., 13 lks. dist., mkd. T32S R5W S33 RS33 BT.  
(thence West on a true line on S. boundary of sec. 33, T32S R5W to the closing cor. of secs. 3 & 4 T33S R5W at 5.58 chs.)

Douglas Co. Surveyors Office - John M. Powell, Frank Jones, Joe Brady, crew - Sept. 1967 - C.S. File 53/52-41

-----  
Found - 1½" Iron pipe at sec. cor.  
Orig. 30" now 50" D.Fir S.18°W., 19.1 ft.  
6" D.Fir now stob, N.40°E., 12.5 ft., scribe visible.  
8" D.Fir now stob, N.8°W., 8.6 ft. scribe visible "R5W".  
New BTs -7" D.Fir N.74°W., 5.9 ft. mkd. T32S R5W S33 CC CS BT  
14" Laurel N.21°E. 16.0 ft mkd T32S R5W S34 CC CS BT

Ronald Quimby - For: Plum Creek Timber Co. - July 2015 - M166-36

-----  
Found - 1½" iron pipe per 1953 survey by Price  
72" tall, 14" partial laurel snag N.21°E., 16.0'  
Mostly rotten fir stob N.40°E., 12.5'  
56" fir S.18°W., 19.1' - healed scar  
11" fir N.74°W., 5.9' - healed scar  
New BTs- 16" fir N.57°E., 18.6'  
17" FIR S.70°E., 17.2'  
BOTH SCRIBED "T32S R5W S34 BT"

Ken Hoffine - For: Lone Rock Timber Co - June 2020 - M177-25

-----  
Found - 1½" iron pipe with washer in middle 1.0 ft above ground level.  
Madrone stub remains bears N.21°E., 15.7 ft (record per M166-36 N.21°E., 16.0 ft)  
66" D.Fir bears S.16½°W., 20.1 ft (rec per M166-36 S.18°W., 19.1 ft) healed face and BT tag  
12" D.Fir bears N.71¾°W., 5.6 feet (rec per M166-36 N.74°W., 5.9 ft) healed face and BT tag.  
18" D.Fir bears N.44¾°E., 19.7 ft (rec per M166-36 N.52°E., 18.6 ft) visible scribing and BT tag.  
18" D.Fir bears S.73¾°E., 16.8 ft (rec per M166-36 S.70°E., 17.2 ft ) visible scribing and BT tag  
Corner lies on steep east facing slope approx 350 feet east of end of rock road 33-5-4.3.

continued next page

TOWNSHIP 32 RANGE 05 POINT IDENTIFIER # 400100

PRIMARY CORNER DESCRIPTION So. Sec. Cor. for 33 and 34 only

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Gregg Neitsch - For: John Hancock Life Insurance Co - 12/2022  
- M181-58

-----  
Found - 1½" dia., galvanized iron pipe, tagged "RS 33"  
60" dia., D.Fir with healed blaze, S.17°05'W., 20.1'  
(rec. S. 16°30'W., 20.1')  
13" dia., D.Fir with healed blaze, N.70°27'W., 5.6'  
(rec. N.71°45'W., 5.6')  
18" dia., D.Fir, visible scar, N.44°46'E., 18.7'  
(rec. N.44°45'E., 19.7')  
18" dia. D.Fir, visible scar, S.73°18'E., 16.8'  
(rec. S.73°45'E., 16.8')  
5' high madrone stub, N.20°27'E., 15.0' (rec.  
N.21°E., 15.7')