

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs 9 & 10

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Original - W.H. Byars, under contract # 152 survey dated June 3, 1871 (DCSO records Vol. 20 Page(s) 8586)

Set ¼ sec. post, from which
A Fir, 8" dia., bears N.30°E., 8 lks.
A Fir, 5" dia., bears S.30°W., 7 lks.

Greg Lang - For: Silver Butte Timber Co - Sept. 1995 - M125-7

Set - 5/8"x30" I.R. w/plastic cap mkd: "LANG SURVEYING"
Spike in the face of a 5 ¾" Fir, bears S.41°47'W.,
43.68', scribed "¼ S9 BT"
Spike in the face of a 21" Fir, bears N.49°55'W.,
89.05', scribed "¼ S9 BT"
Spike in the face of a 7¼" Fir, bears N.61°24'E.,
66.22', scribed "¼ S10 BT"
Spike in the face of a 7" Madrone, bears S.23°22'E.,
24.43', scribed "¼ S10 BT"

BLM dependent resurvey by Kevin G Mulder, Cadastral Surveyor,
under Group No. 2925; Surveyed July/Oct. 2018 - (DCSO records
Vol. 59 Page(s) 23754)

The ¼ sec cor of secs. 9 & 10, reestablished by proportionate
measurement by Lang in 1996. There is no remaining evidence
of the orig. cor., therefore this position is accepted as a
careful and faithful reestablishment of the cor.; monumented
with an iron rod, 5/8" dia., firmly set, projecting 6" above
the ground, with yellow plastic cap mkd. LANG SURVEYING, from
which the remains of bearing trees mkd. by Lang

A madrone snag, 8" dia., bears N.61¼°E., 66.7 ft., with
scribe marks ¼ S10 visible on partially healed upper
blaze and a healed lower blaze.

A madrone, 10" dia., bears S.22½°E., 24.9 ft., with
illegible scribe marks visible on partially healed
double blaze.

A fir, 16" dia., bears S.41¼°W., 44.4 ft., with a healed
double blaze.

A fir, 30" dia., bears N.50¼°W., 89.9 ft., with a healed
double blaze.

At the corner point

Set a stainless steel post, 28 ins. long, 2 1/2" dia., 24
ins. in the ground, directly over the iron rod, with brass
cap mkd.

T32S R5W
¼ S 9 | S 10
2018