

PRIMARY CORNER DESCRIPTION Sec. Cor. for 26, 27, 34 and 35

Alias	Description
Alias	Description
Alias	Description
Alias	Description

Original - W.H. Byars, under contract # 152 survey dated June 3, 1871 (DCSO records Vol. 20 Page(s) 8580)

Set post cor. to secs. 26, 27, 34 and 35, from which
A Fir 36" dia., bears N.10°E., 14 lks.
A Pine 24" dia., bears S.50°E., 26 lks.
A Fir 24" dia., bears S.12°W., 68 lks.
A Pine 24" dia., bears N.42°W., 76 lks.

GLO survey by Oscar F. Thiel, Deputy Surveyor, under Contract #729, dated Dec. 24, 1900 (DCSO records Vol. 20 Page(s) 8614)

The sec. cor.; the old post having disappeared, I set a Pine post, 3 ft. long, 4" sq., with marked sandstone 12x12x10 ins. 24" in the ground, for cor. of secs. 26, 27, 34 and 25, marked T32S S26 on NE.; R5W S35 on SE.; S34 on SW.; and S27 on NW. faces; with 1 notch on S. and 2 notches on E. edges, and witnessed as described by the surveyor general. This cor. stands 15 ft. above creek.

George J. Wenderoth - Wit: F. Dean - Aug. 1951 - C.S. File 41/18 - and C.S. File 45/54, 1952

Found - 40" Fir N.10°E., 9.2 ft., dead.
24" Pine S.50°E., 17.6 ft., stump
30" Fir S.12°W., 44.8 ft., stump
24" Pine N.40°W., 50.1 ft., no marks.
Drive 1½" I.P. for corner.
Scribe - 24" Fir S.54°30'W., 104.8 ft.
28" Pine N.42°W., 51.6 ft.
No other trees available.

Douglas Co. Surveyors Office - John M. Powell, Frank Jones, Joe Brady, crew - July 1967 - C.S. File 53/52-37

Found - 1½" iron pipe at corner.
24" now 27" Fir S.54½°W., 104.8 ft., shows good scar.
28" Pine, now dead, N.42°W., 51.6 ft., scribe visible "S27 BT"
New BTs -10" Pine N.21½°W., 35.8 ft. mkd. T32S R5W S27 CS BT
13" Pine N.33°E., 43.5 ft. mkd. T32S R5W S26 CS BT.
8" D.Fir S.50½°E., 10.8 ft. mkd. T32S R5W S35 CS BT.
This corner lies 150.0 ft. West of Quinnes Creek Road and 1.5 ft. North of E-W fence line.

Fd. OK, Jan. 1981 by Rogers, M 87-12 (Fd. 13" Pine to be N.43°E)
(Cont. Next Page)

PRIMARY CORNER DESCRIPTION Sec Cor for 26, 27, 34 and 35

Alias	Description

Corner Fd. OK, by R. Templin, Feb. 1994 , M 120-35	
Fd. OK by Raymond Brown, L.S. #2391 - For: Dan Folliard & Jamine Graf - Dec. 1994 M 121-50.	
Douglas Co. Surveyors Office - Randall W. Smith, Deputy - Stephen J. Flause - 8/23/2000 - C.S. File 66/16-34 -----	
Found -	1½" I.D. iron pipe protruding 4" out of ground in an I-W fence line. (1952) 24" now rotted to ground Pine stump, bears S.50°E., 17.2 ft. (OBT) 24" now 30" 2½ ft. high rotted Fir stump no scribing found bears S.12°W., 44.8 ft. dist. would be to face. (OBT) 36" now 20" dia., 4 ft. high rotted D.Fir snag, bears N.10°E., 9.2 ft. dist. would be to face (OBT) 24" now down and rotted Pine bears N.42°W., 50.2 ft. (OBT) 24" now 35" dia., 1½ ft. high Fir stump bears S.54½°W., 104.8 ft. (1952) 10" now 20" dia., 1 ft. high Pine stump with scribing "BT", bears N.21½°W., 35.8 ft. (1967) 8" now 14" dia., D.Fir with a fully healed double blaze, bears S.53°E., 10.8 ft. (rec. S.50½°E., 10.8 ft.) 1967 13" now 22" dia., P.Pine with a fully healed double blaze bears N.27°E., 43.5 ft. (Rec. N.33°E., 43.5 ft. 1967) (Rec. N.43°E., 1981) 1967
New -	11" dia., D.Fir double blazed & scribed "T32S R5W S34 CS BT" bears S.36½°W., 43.6 ft. 8" dia., D.Fir double blazed & scribed "T32S R5W S27 CS BT" bears N.71°W., 44.4 ft.
DCSO-GIS Corner visitation - 1/21/2004 - Typed: 2/10/2011 - C.S. File 67/33-1 -----	
Monument -	1½"
Fd. 1½" IP 4" above ground & BTs by Ray Wytcherley - 4/2007 - M152-71	
Fd. 1½" IP per rec by R. Brown 2/2018 - M171-40	
Fd. 1½" IP by Ray Wytcherley - 4/2018 - M174-22	
Fd. 1½" IP per rec by R. Brown 7/2019 - M171-65	