

TOWNSHIP 32 RANGE 05 POINT IDENTIFIER # 500340

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 22 and 23

Alias 037040 Description SSE Cor. Mynatte DLC #37

Alias _____ Description _____

Alias _____ Description _____

Alias _____ Description _____

Original - Survey by Wells Lake, under Contract #54, dated Feb. 19, 1855 - (DCSO records Vol. 20 Page(s) 8562)

Set ¼ sec. post, from which

A Fir 10" dia., bears N.51°E., 56 lks.

A Fir 12" dia., bears S.82°W., 14 lks.

DLC Survey by J.A. Burnett, under Contract #75 dated Nov. 22, 1856

Beginning survey at the ¼ sec. post between secs. 22 and 23, from which

A Fir 4" dia., bears N.52°W., 25 lks.

W. F. Briggs, Co. Surveyor - For: H.L. Wilson (Levens Estate) July 1900 - Vol. 2 Page 95

Set new post as per original BT standing to wit:

W.Fir 20" dia., bears N.51°E., 56 lks.

R.Fir 12" dia., bears S.82°W., 13 lks.

Survey by Geo. J. Wenderoth - June 1957 - C.S. File 45/164

Car Axle.

16" W.Oak N.62°30'W., 46.5 ft.

18" Balm S.81°05'E., 114.7 ft.

Cor. Fd. OK, DCSO, John Powell, August 1967

Douglas Co. Surveyors Office - S.J. Flause, Deputy - T. Plouff, S. Means, crew - April 23, 1980 - C.S. File 61/6-38

Found - A car axle approx. 1" dia., protruding approx. 0.5 ft. from ground, firmly set.

Possible remains of S.82°W., orig. BT, this is a rotted stump. We find no evidence of blazes or scribing.

An 18" now 29" cottonwood (Balm) bears S.78°E., 115.5 ft. (Rec. S.81°05'E., 114.7 ft.) healed single blaze, no scribing visible.

An orig. 16" now 28" W.Oak bears N.60°W., 46.5 ft. (Rec. N.62°30'W., 46.5 ft.) healed single blaze, no scribing visible.)

We tag trees and mark tags with new bearings and distances as above. Because record evidence does not tie back to orig. corner, WE DO NOT SET brass cap, but only perpetuated ¼ corner position as determined by Wenderoth in 1957.

(Cont. Next Page)

TOWNSHIP 32 RANGE 05 POINT IDENTIFIER # 500340

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 22 and 23

Alias 037040 Description SSE Cor. DLC #37
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

New tags as mentioned in "found accessories". No suitable trees available in NE and SW quadrants.

BLM resurvey by Virgil L. Stanger, cadastral surveyor, under Group #1145, surveyed May/Aug. 1983 - (DCSO records Vol. 47 Page(s) 17877-78)

(Cont. Next Page)

The ¼ sec. cor., reestablished by proportionate measurement and recorded by Wenderoth in 1953 (? , date) and is accepted as the best available evidence of the position of the original corner, monumented with an automobile axle 1" dia., firmly set, projecting 2" above ground, from which bearing trees mkd. by Wenderoth:

A Cottonwood 31" dia., bears S.82°E., 175 lks. dist., with healed blaze.

A W.Oak 16" dia., bears N.63°W., 70½ lks. dist., with healed blaze.

At the corner point

Set an iron post, 28 ins. long, 2 1/2 ins. dia., 21 ins. in the ground, directly over axle, with brass cap marked

T 32 S R 5 W
 ¼
 S 22 | S 23
 1983

Corner is located on South edge of dirt road, 15 lks. wide, bears E. and W.

Douglas Co. Surveyors Office - Randall Smith & Stephen Flause
- CS 64/52-3 - 7/13/94

Found - 3¼" Brass cap on a 2½" O.D. Iron pipe protruding 5" above ground (1983 BLM).

U.S. DEPT. OF THE INTERIOR

T 32 S R 5 W
 S22 | S23 ¼
 1983

BUR. OF LAND MANAGEMENT

16" W. Oak now 32" dia., B. Oak with a fully healed single blaze, bears N.63°W. 46.5', (agrees with rec)

18" Balm now 36" dia., 15' high cottonwood stump with a fully healed blaze, bears S.82°E., 115.5' (agrees with rec) to be cut down to ground in near future.

(Cont. Next Page)

TOWNSHIP 32 RANGE 05 POINT IDENTIFIER # 500340

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 22 and 23

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

New Accessories -

7" dia., Chinese Elm double blazed & scribed "X BT",
bears S.64½°E. 12.2'.

Power Pole # "E 643", bears N.30½°E. 53.4'.

14" dia., B. Oak double blazed & scribed "¼ S22 CS
BT", bears N.11°W 79.5'.

Found OK by D. Edwards, Oct. 2003 - M143-13