

TOWNSHIP 32 RANGE 05 POINT IDENTIFIER # 540100

PRIMARY CORNER DESCRIPTION So. 1/4 Cor. Sec. 35 only

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Original - Butler Ives and George W. Hyde, under Contract #39, dated January 4, 1854 - (DCSO records Vol. 20 Page(s) 8547)

-----  
Set qr. sec. post, from which  
A Laurel 4" dia., bears North, 12 lks.  
A Fir 3" dia., bears S.13°E., 19 lks.

GL0 survey by Edward F. Sharp, Deputy Surveyor, under Contract #617, dated June 3, 1893 (DCSO records Vol. 21 Page(s) 8969)

-----  
The ¼ sec. cor. on the S. bdy. of Sec. 35, T32S R5W which is post, 3" square, 12" above ground, from which  
A Laurel 4" dia., bears North, 12 lks. with well defined blazes.  
A Fir 3" dia., bears S.13°E., 19 lks. with well defined blazes.

GL0 survey by Oscar F. Thiel, Deputy Surveyor, under Contract #729, dated Dec. 24, 1900 and special instructions dated Sept. 12, 1901 (DCSO records Vol. 20 Page(s) 8616-17)

-----  
The ¼ sec. cor. is gone, only stump of SE. BT remains; Set a Fir post, 3 ft. long, 3" sq., 24" in the ground for ¼ sec. cor., marked S C ¼ S35 on N. face and 2 on S. face, from which  
A Fir 10" dia., bears N.64°W., 26 lks. dist., marked S C ¼ S35 BT.  
A Fir 50" dia., bears S.52°E., 71 lks. dist., marked S C ¼ S2 BT.

Ben B. Irving, D.C.S. - Wit: N.E. Richardson; Frank Kruse - June 11, 1930 - Vol. 4 Pg. 9; C.S. File 37/23; and RM 1-11 (and "old" corner book, page 171)

-----  
Post in place but rotted off. 50" Fir bT as decribed in Govt. field notes.  
Drove 1¼" x 60" Iron pipe for corner with 6" sq. Yewood post alongside.  
A 16" Fir N.13°W., 108 lks.  
Reblazed and scribed orig. BT, a 50" Fir S.52°E., 71 lks.

George J. Wenderoth - 1955 - C.S. File 46/109 and C.S. File 45/54, 1952

-----  
1¼" pipe, from which  
(Cont. Next Page)

TOWNSHIP 32 RANGE 05 POINT IDENTIFIER # 540100

PRIMARY CORNER DESCRIPTION So. 1/4 Cor. for Sec. 35 only

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

20" Fir N.13°W., 71.2 ft.  
14" Fir N.72°50'W., 115.1 ft.

Corner OK, Aug. 1967, DCSO, John Powell C.S. File 53/52-14

BLM resurvey by Joseph Gawron; John Jelley; Rollin Aanrud, Cadastral surveyors, under Group #'s 350 and 566, surveyed March 1965/Dec. 1967 (DCSO records Vol. 34 Page(s) 13976)

-----  
The Ives and Hyde standard ¼ sec. cor. of sec. 35, rehabilitated by Thiel in 1901, monumented with an iron pipe 2½" dia., firmly set, protruding 4" from the ground, alongside of which is a yew post, 4" sq., 36" high, firmly set, mkd. ¼ S35 on the NW., SC on the NE.; and CS on the SE. face, from which the remains of a bearing tree mkd. by Thiel in 1901:

A sawed D.Fir stump 60" dia., bears S.52°E., 71 lks. dist., mkd. T on a bark blaze.

and bearing trees mkd. by the County Surveyor:

A D.Fir 27" dia., bears N.15°E., 109 lks. dist., with healed blaze.

A D.Fir 16" dia., bears N.74°W., 174 lks. dist., with a healed blaze.

At the corner point

Set an iron post, 28 ins. long, 2 1/2 ins. dia., 24 ins. in the ground, directly over the iron pipe, with brass cap marked

T 32 S R 5 W  
S C  
¼ S 35  
1965

from which

An Incense Cedar 8" dia., bears N.43°E., 99 lks. dist., mkd. ¼ S35 SC BT.

A D.Fir 12" dia., bears N.41°W., 74 lks. dist., mkd. ¼ S35 SC BT.

Reset the wooden post alongside the iron post.

BLM dependent resurvey by Kevin G Mulder, Cadastral Surveyor, under Group No. 3006; Surveyed April 2021/Nov. 2022 - (DCSO records Vol. 59 Page(s) 24110-1)

-----  
The standard ¼ sec. cor. of sec. 35 only, T32S R5W determined at record from the remains of bearing trees reported by Gawron et al., in 1965-67

A cedar, 25" dia., bears N.31¾°E., 65.3 ft., with a healed blaze. (Record, N.43°E.)

A rotted fir stump, size indeterminate, bears S.52°E., 46.9 ft., no marks visible. (Original) Cont.

TOWNSHIP 32 RANGE 05 POINT IDENTIFIER # 540100

PRIMARY CORNER DESCRIPTION So. 1/4 Cor. Sec. 35 only

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

A fir, 31" dia., bears N.73°W., 114.8 ft., with a healed blaze. (Record, N.74°W.)

A fir, 24" dia., bears N.41°W., 48.8 ft., with a healed blaze.

At the corner point

Set a stainless steel post, 28" long, 2½" dia., 34" in the ground, with brass cap mkd.

SC  
T 32S R 5W  
¼ S 35  
2021

and a new reference monument

An iron rod, 30" long, 5/8" dia., set 28" in the ground, bears N.20°48'49"W., 49.30 ft., with aluminum cap mkd.  
RM SC ¼ S35 49.30 FT TO COR 2021 and an arrow pointing to the cor.

The cor. is located in a gravel road, 18 ft. wide, bears S.45°E. and N.45°W.

The iron post set by Gawron et al., in 1965-67 was not recovered.